BS EN 15605:2010

BSI Standards Publication

Copper and copper alloys — Inductively coupled plasma optical emission spectrometry

NO COPYING WITHOUT BSI PERMISSION EXCEPT AS PERMITTED BY COPYRIGHT LAW

raising standards worldwide™

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

National foreword

This British Standard is the UK implementation of EN 15605:2010.

The UK participation in its preparation was entrusted to Technical Committee NFE/34, Copper and copper alloys.

A list of organizations represented on this committee can be obtained on request to its secretary.

This publication does not purport to include all the necessary provisions of a contract. Users are responsible for its correct application.

© BSI 2010

ISBN 978 0 580 66406 9

ICS 77.120.30

Compliance with a British Standard cannot confer immunity from legal obligations.

This British Standard was published under the authority of the Standards Policy and Strategy Committee on 31 August 2010

Amendments issued since publication

Date	Text affected

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

EUROPEAN STANDARD
NORME EUROPÉENNE
EUROPÄISCHE NORM

EN 15605

July 2010

ICS 77.120.30

Supersedes CEN/TS 15605:2007

English Version

Copper and copper alloys - Inductively coupled plasma optical emission spectrometry

Cuivre et alliages de cuivre - Analyse par spectrométrie d'émission optique avec source à plasma induit par haute fréquence

Kupfer und Kupferlegierungen - Optische Emissionsspektrometrie mit induktiv gekoppelter Plasmaanregung

This European Standard was approved by CEN on 12 June 2010.

CEN members are bound to comply with the CEN/CENELEC Internal Regulations which stipulate the conditions for giving this European Standard the status of a national standard without any alteration. Up-to-date lists and bibliographical references concerning such national standards may be obtained on application to the CEN Management Centre or to any CEN member.

This European Standard exists in three official versions (English, French, German). A version in any other language made by translation under the responsibility of a CEN member into its own language and notified to the CEN Management Centre has the same status as the official versions.

CEN members are the national standards bodies of Austria, Belgium, Bulgaria, Croatia, Cyprus, Czech Republic, Denmark, Estonia, Finland, France, Germany, Greece, Hungary, Iceland, Ireland, Italy, Latvia, Lithuania, Luxembourg, Malta, Netherlands, Norway, Poland, Portugal, Romania, Slovakia, Slovenia, Spain, Sweden, Switzerland and United Kingdom.

EUROPEAN COMMITTEE FOR STANDARDIZATION
COMITÉ EUROPÉEN DE NORMALISATION
EUROPÄISCHES KOMITEE FÜR NORMUNG

Management Centre: Avenue Marnix 17, B-1000 Brussels

© 2010 CEN All rights of exploitation in any form and by any means reserved worldwide for CEN national Members.

Ref. No. EN 15605:2010: E

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

Contents

Page

Foreword 3
1 Scope 4
2 Normative references 6
3 Principle 6
4 Reagents 6
5 Apparatus 11
6 Sampling 11
7 Procedure 11
7.1 Method A: Coppers 11
7.2 Method B: Copper-zinc alloys 15
7.3 Method C: Copper-tin alloys 19
7.4 Method D: Copper-aluminium alloys 23
7.5 Method E: Copper-beryllium alloys 27
7.6 Method F: Copper-nickel alloys 31
8 Expression of results 35
9 Precision 35
9.1 Method A — Coppers 35
9.2 Method B — Copper-zinc alloys 36
9.3 Method C — Copper-tin alloys 37
9.4 Method D — Copper-aluminium alloys 38
9.5 Method E — Copper-beryllium alloys 39
9.6 Method F — Copper-nickel alloys 40
10 Test report 40
Annex A (informative) **Optical emission spectrometer (OES) — Suggested performance criteria to be checked** 41
Annex B (informative) **Inductively coupled plasma emission spectrometry method for the analysis of Copper-tin-lead alloys** 43
Bibliography 49

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

Foreword

This document (EN 15605:2010) has been prepared by Technical Committee CEN/TC 133 “Copper and copper alloys”, the secretariat of which is held by DIN.

This European Standard shall be given the status of a national standard, either by publication of an identical text or by endorsement, at the latest by January 2011, and conflicting national standards shall be withdrawn at the latest by January 2011.

Attention is drawn to the possibility that some of the elements of this document may be the subject of patent rights. CEN [and/or CENELEC] shall not be held responsible for identifying any or all such patent rights.

This document supersedes CEN/TS 15605:2007.

Within its programme of work, Technical Committee CEN/TC 133 requested CEN/TC 133/WG 10 "Methods of Analysis" to revise the following Technical Specification:

CEN/TS 15605, *Copper and copper alloys — Inductively coupled plasma optical emission spectrometry*

In comparison with the first edition of CEN/TS 15605:2007, the following significant technical changes were made:

Revision from a Technical Specification to a European Standard;

Method G (specifying the analysis of Copper-tin-lead alloys) is edited under an informative basis (see Annex B), taking into account the mediocrity of the precision criteria related to this method;

Precision criteria for methods A and E were added;

Precision criteria for methods B, C, D and F were improved and up-dated.

According to the CEN/CENELEC Internal Regulations, the national standards organizations of the following countries are bound to implement this European Standard: Austria, Belgium, Bulgaria, Croatia, Cyprus, Czech Republic, Denmark, Estonia, Finland, France, Germany, Greece, Hungary, Iceland, Ireland, Italy, Latvia, Lithuania, Luxembourg, Malta, Netherlands, Norway, Poland, Portugal, Romania, Slovakia, Slovenia, Spain, Sweden, Switzerland and United Kingdom.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

1 Scope

This European Standard specifies six inductively coupled plasma emission spectrometry methods (A to F) for the determination of alloying elements and impurities in copper and copper alloys in the form of unwrought, wrought and cast products.

A complementary method, for the analysis of Copper-tin-lead alloys, is described in Annex B (informative). The precision criteria concerning this method do not reach the suitable level, for all the elements specified (zinc and phosphorus, namely).

These methods are applicable to the elements listed in Tables 1 to 6 within the composition ranges shown:

Table 1 — Coppers

Element	Mass fraction %	
	min	max
Sn	0,02	0,60
Pb	0,02	0,60
Zn	0,02	0,60
Fe	0,01	0,60
Ni	0,01	0,60
Mn	0,01	0,60
Al	0,02	0,60
P	0,01	0,40
Be	0,01	0,60
Co	0,01	0,60
Cd	0,01	0,60

Table 2 — Copper-zinc alloys

Element	Mass fraction %	
	min.	max.
Sn	0,05	2,00
Pb	0,03	4,00
Zn	10,00	42,00
Fe	0,01	5,00
Ni	0,02	4,00
Mn	0,01	6,00
P	0,01	0,40
Al	0,02	9,00
As	0,01	0,20

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

Table 3 — Copper-tin alloys

Element	Mass fraction %	
	min.	max.
Sn	3,00	16,00
Pb	0,01	9,00
Zn	0,03	6,00
Fe	0,01	1,00
Ni	0,05	7,00
Mn	0,01	0,40
P	0,01	0,60
Al	0,01	0,50
Sb	0,02	1,60
As	0,02	0,25

Table 4 — Copper-aluminium alloys

Element	Mass fraction %	
	min.	max.
Sn	0,02	0,50
Pb	0,03	0,50
Zn	0,03	1,00
Fe	0,05	7,00
Ni	0,10	8,00
Mn	0,01	5,00
Al	6,00	14,00
Cd	0,01	0,50
Mg	0,002	0,15

Table 5 — Copper-beryllium alloys

Element	Mass fraction %	
	min.	max.
Sn	0,02	0,20
Pb	0,01	0,20
Zn	0,03	0,20
Fe	0,03	0,30
Ni	0,04	2,50
Mn	0,006	0,15
Al	0,03	0,20
Be	0,08	4,00
Co	0,03	4,00

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

Table 6 — Copper-nickel alloys

Element	Mass fraction %	
	min.	max.
Sn	0,10	0,50
Pb	0,03	0,50
Zn	0,04	2,00
Fe	0,10	4,00
Ni	7,00	35,00
Mn	0,02	3,00
Al	0,02	0,50

NOTE 1 The ranges specified for each method can be extended or adapted, for the determination of lower mass fractions.

NOTE 2 Other elements may be included. However such elements and their mass fractions should be carefully checked, taking into account interference, sensitivity, resolution and linearity criteria for each instrument and each wavelength.

2 Normative references

The following referenced documents are indispensable for the application of this document. For dated references, only the edition cited applies. For undated references, the latest edition of the referenced document (including any amendments) applies.

ISO 1811-1, *Copper and copper alloys — Selection and preparation of samples for chemical analysis — Part 1: Sampling of cast unwrought products*

ISO 1811-2, *Copper and copper alloys — Selection and preparation of samples for chemical analysis — Part 2: Sampling of wrought products and castings*

3 Principle

Dissolution of a test portion with hydrochloric and nitric acids. After suitable dilution and addition of an internal reference element, nebulization of the solution into an inductively coupled plasma emission spectrometer and measurement of the intensity of the emitted light, including that of the internal reference element.

4 Reagents

During the analysis, use only reagents of recognised analytical grade and only distilled water or water of equivalent purity.

The same reagents should be used for the preparation of calibration solutions and of sample solutions.

4.1 Hydrochloric acid, HCl (ρ = 1,19 g/ml)

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

4.2 Hydrochloric acid, solution 1 + 1

Add 500 ml of hydrochloric acid (4.1) to 500 ml of water.

4.3 Nitric acid, HNO_3 (ρ = 1,40 g/ml)

4.4 Nitric acid, solution 1 + 1

Add 500 ml of nitric acid (4.3) to 500 ml of water.

4.5 Hydrofluoric acid, HF (ρ = 1,13 g/ml)

4.6 Sulphuric acid, H_2SO_4 (4,5 mol/l)

4.7 Electrolytic copper

4.8 Zinc granules of 99,999 % purity

4.9 Aluminium stock solution, 10 g/l Al

Weigh (5 ± 0,001) g of aluminium (Al ≥ 99,99 %) and transfer into a 600 ml beaker. Add 250 ml of hydrochloric acid solution (4.2) and cover with a watch glass. After cooling to room temperature, transfer the solution quantitatively into a 500 ml one-mark volumetric flask, dilute to the mark with water and mix well.

1 ml of this solution contains 10 mg of Al.

4.10 Aluminium stock solution, 1 g/l Al

Weigh (1 ± 0,001) g of aluminium (Al ≥ 99,99 %) and transfer into a 400 ml beaker. Add 50 ml of hydrochloric acid solution (4.2) and cover with a watch glass. After cooling to room temperature, transfer the solution quantitatively into a 1 000 ml one-mark volumetric flask, dilute to the mark with water and mix well.

1 ml of this solution contains 1 mg of Al.

4.11 Antimony stock solution, 1 g/l Sb

Weigh (0,5 ± 0,001) g of antimony (Sb ≥ 99,99 %) and transfer into a 250 ml beaker. Add 50 ml of hydrochloric acid (4.1) and 25 ml of nitric acid solution (4.4) and cover with a watch glass. Heat gently until the metal is dissolved. After cooling to room temperature, transfer the solution quantitatively into a 500 ml one-mark volumetric flask, containing 100 ml of hydrochloric acid (4.1), dilute to the mark with water and mix well.

1 ml of this solution contains 1 mg of Sb.

4.12 Arsenic stock solution, 1 g/l As

Weigh (0,5 ± 0,001) g of arsenic (As ≥ 99,99 %) and transfer into a 250 ml beaker. Add 20 ml of nitric acid solution (4.4) and cover with a watch glass. Heat gently until the metal is dissolved. After cooling to room temperature, transfer the solution quantitatively into a 500 ml one-mark volumetric flask, dilute to the mark with water and mix well.

1 ml of this solution contains 1 mg of As.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

4.13 Beryllium stock solution, 5 g/l Be

Weigh (1 ± 0,001) g of beryllium (Be ≥ 99,99 %) and transfer into a 250 ml beaker. Add 40 ml of hydrochloric acid (4.1) and cover with a watch glass. Heat gently until the metal is dissolved. After cooling to room temperature, transfer the solution quantitatively into a 200 ml one-mark volumetric flask, dilute to the mark with water and mix well.

1 ml of this solution contains 5 mg of Be.

4.14 Beryllium stock solution, 1 g/l Be

Weigh (0,5 ± 0,001) g of beryllium (Be ≥ 99,99 %) and transfer into a 250 ml beaker. Add 20 ml of hydrochloric acid (4.1) and cover with a watch glass. Heat gently until the metal is dissolved. After cooling to room temperature, transfer the solution quantitatively into a 500 ml one-mark volumetric flask, dilute to the mark with water and mix well.

1 ml of this solution contains 1 mg of Be.

4.15 Cadmium stock solution, 1 g/l Cd

Weigh (1 ± 0,001) g of cadmium (Cd ≥ 99,99 %) and transfer into a 400 ml beaker. Add 10 ml of nitric acid (4.3) and cover with a watch glass. Heat gently until the metal is dissolved, then boil until nitrous fumes have been expelled. After cooling to room temperature, transfer the solution quantitatively into a 1 000 ml one-mark volumetric flask, dilute to the mark with water and mix well.

1 ml of this solution contains 1 mg of Cd.

4.16 Cobalt stock solution, 5 g/l Co

Weigh (1 ± 0,001) g of cobalt (Co ≥ 99,99 %) and transfer into a 250 ml beaker. Add 10 ml of hydrochloric acid (4.1) and 10 ml of nitric acid (4.3) and cover with a watch glass. Heat gently until the metal is dissolved, then boil until nitrous fumes have been expelled. After cooling to room temperature, transfer the solution quantitatively into a 200 ml one-mark volumetric flask, dilute to the mark with water and mix well.

1 ml of this solution contains 5 mg of Co.

4.17 Cobalt stock solution, 1 g/l Co

Weigh (0,5 ± 0,001) g of cobalt (Co ≥ 99,99 %) and transfer into a 250 ml beaker. Add 5 ml of hydrochloric acid (4.1) and 5 ml of nitric acid (4.3) and cover with a watch glass. Heat gently until the metal is dissolved, then boil until nitrous fumes have been expelled. After cooling to room temperature, transfer the solution quantitatively into a 500 ml one-mark volumetric flask, dilute to the mark with water and mix well.

1 ml of this solution contains 1 mg of Co.

4.18 Iron stock solution, 5 g/l Fe

Weigh (5 ± 0,001) g of iron (Fe ≥ 99,99 %) and transfer into a 400 ml beaker. Add 100 ml of hydrochloric acid (4.1) and 50 ml of nitric acid solution (4.4) and cover with a watch glass. Heat gently until the metal is dissolved, then boil until nitrous fumes have been expelled. After cooling to room temperature, transfer the solution quantitatively into a 1 000 ml one-mark volumetric flask, dilute to the mark with water and mix well.

1 ml of this solution contains 5 mg of Fe.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

4.19 Iron stock solution, 1 g/l Fe

Weigh (1 ± 0,001) g of iron (Fe ≥ 99,99 %) and transfer into a 250 ml beaker. Add 20 ml of hydrochloric acid (4.1) and 10 ml of nitric acid solution (4.4) and cover with a watch glass. Heat gently until the metal is dissolved, then boil until nitrous fumes have been expelled. After cooling to room temperature, transfer the solution quantitatively into a 1 000 ml one-mark volumetric flask, dilute to the mark with water and mix well.

1 ml of this solution contains 1 mg of Fe.

4.20 Lead stock solution, 5 g/l Pb

Weigh (2,5 ± 0,001) g of lead (Pb ≥ 99,99 %) and transfer into a 400 ml beaker. Add 50 ml of nitric acid solution (4.4) and cover with a watch glass. Heat gently until the metal is dissolved, then boil until nitrous fumes have been expelled. After cooling to room temperature, transfer the solution quantitatively into a 500 ml one-mark volumetric flask, dilute to the mark with water and mix well.

1 ml of this solution contains 5 mg of Pb.

4.21 Lead stock solution, 1 g/l Pb

Weigh (1 ± 0,001) g of lead (Pb ≥ 99,99 %) and transfer into a 250 ml beaker. Add 20 ml of nitric acid solution (4.4) and cover with a watch glass. Heat gently until the metal is dissolved, then boil until nitrous fumes have been expelled. After cooling to room temperature, transfer the solution quantitatively into a 1 000 ml one-mark volumetric flask, dilute to the mark with water and mix well.

1 ml of this solution contains 1 mg of Pb.

4.22 Magnesium stock solution, 1 g/l Mg

Weigh (1 ± 0,001) g of magnesium (Mg ≥ 99,99 %) and transfer into a 250 ml beaker. Add 50 ml of nitric acid solution (4.4) and cover with a watch glass. Heat gently until the metal is dissolved, then boil until nitrous fumes have been expelled. After cooling to room temperature, transfer the solution quantitatively into a 1 000 ml one-mark volumetric flask, dilute to the mark with water and mix well.

1 ml of this solution contains 1 mg of Mg.

4.23 Manganese stock solution, 5 g/l Mn

The manganese used to prepare the solution is released from superficial oxide possibly present by introducing a few grams of metal in a 250 ml beaker containing 60 ml to 80 ml of sulphuric acid (4.6) and approximately 100 ml of water. Shake and after a few seconds, allow the solution to settle and add water. Repeat the water cleaning several times. Remove the metallic manganese, introduce it into acetone, allow to settle and dry the metal in an oven at 100 °C for 2 min. Cool in a desiccator.

Weigh (5 ± 0,001) g of this purified manganese and transfer into a 400 ml beaker. Add 50 ml of hydrochloric acid (4.1) and 125 ml of nitric acid solution (4.4) and cover with a watch glass. Heat gently until the metal is dissolved. After cooling to room temperature, transfer the solution quantitatively into a 1 000 ml one-mark volumetric flask, dilute to the mark with water and mix well.

1 ml of this solution contains 5 mg of Mn.

4.24 Manganese stock solution, 1 g/l Mn

Weigh (1 ± 0,001) g of manganese, purified as described in 4.23 and transfer into a 250 ml beaker. Add 10 ml of hydrochloric acid (4.1) and 25 ml of nitric acid solution (4.4) and cover with a watch glass. Heat gently until the metal is dissolved. After cooling to room temperature, transfer the solution quantitatively into a 1 000 ml one-mark volumetric flask, dilute to the mark with water and mix well.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

1 ml of this solution contains 1 mg of Mn.

4.25 Nickel stock solution, 10 g/l Ni

Weigh (5 ± 0,001) g of nickel (Ni ≥ 99,99 %) and transfer into a 400 ml beaker. Add 125 ml of nitric acid solution (4.4) and cover with a watch glass. Heat gently until the metal is dissolved, then boil until nitrous fumes have been expelled. After cooling to room temperature, transfer the solution quantitatively into a 500 ml one-mark volumetric flask, dilute to the mark with water and mix well.

1 ml of this solution contains 10 mg of Ni.

4.26 Nickel stock solution, 5 g/l Ni

Weigh (5 ± 0,001) g of nickel (Ni ≥ 99,99 %) and transfer into a 400 ml beaker. Add 125 ml of nitric acid solution (4.4) and cover with a watch glass. Heat gently until the metal is dissolved, then boil until nitrous fumes have been expelled. After cooling to room temperature, transfer the solution quantitatively into a 1 000 ml one-mark volumetric flask, dilute to the mark with water and mix well.

1 ml of this solution contains 5 mg of Ni.

4.27 Nickel stock solution, 1 g/l Ni

Weigh (1 ± 0,001) g of nickel (Ni ≥ 99,99 %) and transfer into a 250 ml beaker. Add 25 ml of nitric acid solution (4.4) and cover with a watch glass. Heat gently until the metal is dissolved, then boil until nitrous fumes have been expelled. After cooling to room temperature, transfer the solution quantitatively into a 1 000 ml one-mark volumetric flask, dilute to the mark with water and mix well.

1 ml of this solution contains 1 mg of Ni.

4.28 Phosphorus stock solution, 1 g/l P

Weigh (4,394 ± 0,001) g of dried potassium dihydrogen phosphate into a 1 000 ml one-mark volumetric flask and dissolve it with water. Dilute to the mark with water and mix well.

1 ml of this solution contains 1 mg of P.

4.29 Tin stock solution, 10 g/l Sn

Weigh (5 ± 0,001) g of tin (Sn ≥ 99,99 %) and transfer into a 400 ml beaker. Add 50 ml of hydrochloric acid (4.1) and cover with a watch glass. Heat gently until the metal is dissolved. After cooling to room temperature, transfer the solution quantitatively into a 500 ml one-mark volumetric flask, dilute to the mark with water and mix well.

1 ml of this solution contains 10 mg of Sn.

4.30 Tin stock solution, 5 g/l Sn

Weigh (2,5 ± 0,001) g of tin (Sn ≥ 99,99 %) and transfer into a 400 ml beaker. Add in 50 ml of hydrochloric acid (4.1) and cover with a watch glass. Heat gently until the metal is dissolved. After cooling to room temperature, transfer the solution quantitatively into a 500 ml one-mark volumetric flask, dilute to the mark with water and mix well.

1 ml of this solution contains 5 mg of Sn.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

4.31 Tin stock solution, 1 g/l Sn

Weigh (0,5 ± 0,001) g of tin (Sn ≥ 99,99 %) and transfer into a 250 ml beaker. Add 50 ml of hydrochloric acid (4.1) and cover with a watch glass. Heat gently until the metal is dissolved. After cooling to room temperature, transfer the solution quantitatively into a 500 ml one-mark volumetric flask, dilute to the mark with water and mix well.

1 ml of this solution contains 1 mg of Sn.

4.32 Zinc stock solution, 10 g/l Zn

Weigh (5 ± 0,001) g of zinc (Zn ≥ 99,99 %) and transfer into a 400 ml beaker. Add 250 ml of hydrochloric acid solution (4.2) and cover with a watch glass. Heat gently until the metal is dissolved. After cooling to room temperature, transfer the solution quantitatively into a 500 ml one-mark volumetric flask, dilute to the mark with water and mix well.

1 ml of this solution contains 10 mg of Zn.

4.33 Zinc stock solution, 1 g/l Zn

Weigh (1 ± 0,001) g of zinc (Zn ≥ 99,99 %) and transfer into a 400 ml beaker. Add 50 ml of hydrochloric acid solution (4.2) and cover with a watch glass. Heat gently until the metal is dissolved. After cooling to room temperature, transfer the solution quantitatively into a 1 000 ml one-mark volumetric flask, dilute to the mark with water and mix well.

1 ml of this solution contains 1 mg of Zn.

4.34 Internal standard solution, 1g/l Yttrium in 0,5 mol/l nitric acid.

5 Apparatus

Optical emission spectrometer (OES), equipped with inductively coupled plasma (ICP) and nebulization systems.

The instrument used will be considered satisfactory if, after optimizing in accordance with the manufacturer's instructions, it meets the performance criteria given in Annex A.

6 Sampling

Sampling shall be carried out in accordance with ISO 1811-1 or ISO 1811-2 as appropriate.

Test samples shall be in the form of fine chips, drillings or millings, e.g. with a maximum thickness of 0,5 mm.

7 Procedure

7.1 Method A: Coppers

7.1.1 Preparation of the test portion solution

7.1.1.1 Test portion

Weigh (1 ± 0,001) g of the test sample.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

7.1.1.2 Test portion solution 5 g/l

Transfer the test portion (7.1.1.1) into a 250 ml beaker.

Add 20 ml of hydrochloric acid solution (4.2) and 5 ml of nitric acid (4.3). Cover with a watch glass and heat gently until the sample is completely dissolved, then heat to boiling. Allow to cool. Rinse the cover and the walls of the beaker with water.

Transfer the dissolved test portion into a 200 ml one-mark volumetric flask containing 10 ml of hydrochloric acid (4.1). Dilute to the mark with water and mix well.

7.1.1.3 Test portion solution 1 g/l

In order to obtain solutions with 1 g/l concentration, pipette exactly 20 ml of the test portion solution (7.1.1.2) into a 100 ml one-mark volumetric flask containing 5 ml of hydrochloric acid (4.1) and 5 ml of yttrium solution (4.34). Dilute to the mark with water and mix well.

7.1.2 Check test

Make a preliminary check of the apparatus by preparing a solution of a copper reference material or a synthetic sample containing known amounts of the elements listed in Table 1 and carrying out the procedure specified in 7.1.4.

7.1.3 Establishment of the calibration curves

7.1.3.1 Preparation of the calibration solutions

7.1.3.1.1 General

In all cases the acidity of the calibration solutions shall be similar to that of the test portion solutions.

If, for measurement purposes, a blank is required, prepare a solution containing only the same amounts of acids as in the test solution.

7.1.3.1.2 Preparation of the 5 g/l calibration solutions, using mono-elemental solutions

Weigh the quantities of copper (4.7) shown in Table 7 and introduce them into each of a series of 250 ml beakers.

Add 20 ml of hydrochloric acid solution (4.2) and 5 ml of nitric acid (4.3) to each beaker. Cover with a watch glass and heat gently in order to dissolve the copper. Rinse the cover and the walls of the beaker with water and heat to boiling. Allow to cool and transfer each copper solution into a 200 ml one-mark volumetric flask containing 10 ml of hydrochloric acid (4.1).

Transfer the volumes of the elemental solutions of Sn, Pb, Zn, Fe, Ni, Mn, P, Al, Be, Co and Cd shown in Table 7 to each volumetric flask. Dilute to the mark with water and mix well.

7.1.3.1.3 Preparation of the 1 g/l calibration solutions

Dilute accurately the 5 g/l calibration solutions (7.1.3.1.2) in order to obtain 1 g/l calibration solutions.

Pipette exactly 20 ml of the 5 g/l calibration solutions (7.1.3.1.2) into 100 ml one-mark volumetric flasks each containing 5 ml of hydrochloric acid (4.1) and 5 ml of yttrium solution (4.34). Dilute to the mark with water and mix well.

Not for Resale
Provided by IHS

No reproduction or networking permitted without license from IHS

Table 7 — Method A — Composition of the 5 g/l calibration solutions

Element	Label			Drift survey solution
	P1	P2	P3	(see 7.1.3.3)
Cu (4.7)	976,3 mg 97,63 %	973,3 mg 97,33 %	979,4 mg 97,94 %	988,0 mg 98,80 %
Sn (4.31)	0,2 mg 0,02 %[a]	0,5mg 0,05 %[b]	6,0 mg 6 ml 0,60 %	1,0 mg 1 ml 0,10 %
Pb (4.21)	6,0 mg 6 ml	0,5mg 0,05 %[c]	0,2mg 0,02 %[d]	1,0 mg 1 ml 0,10 %
Zn (4.33)	0,2mg 0,02 %[e]	0,5 mg 0,05 %[f]	6,0 mg 6 ml 0,60 %	1,0 mg 1 ml 0,10 %
Fe (4.19)	0,5 mg 0,05 %[g]	6,0 mg 6 ml 0,60 %	0,1 mg 0,01 %[h]	1,0 mg 1 ml 0,10 %
Ni (4.27)	0,1 mg 0,01 %[i]	6,0 mg 6 ml 0,60 %	0,5 mg 0,05 %[j]	1,0 mg 1 ml 0,10 %
Mn (4.24)	6,0 mg 6 ml 0,60 %	0,1 mg 0,01 %[k]	0,5 mg 0,05 %[l]	1,0 mg 1 ml 0,10 %
P (4.28)	4,0 mg 4 ml 0,40 %	0,1 mg 0,01 %[m]	0,5 mg 0,05 %[n]	2,0 mg 2 ml 0,20 %
Al (4.10)	6,0 mg 6 ml 0,60 %	0,5 mg 0,05 %[o]	0,2mg 0,02 %[p]	1,0 mg 1 ml 0,10 %
Be (4.14)	0,5 mg 0,05 %[q]	6,0 mg 6 ml 0,60 %	0,1 mg 0,01 %[r]	1,0 mg 1 ml 0,10 %
Co (4.17)	0,1 mg 0,01 %[s]	6,0 mg 6 ml 0,60 %	0,5 mg 0,05 %[t]	1,0 mg 1 ml 0,10 %
Cd (4.15)	0,1 mg 0,01 %[u]	0,5 mg 0,05 %[v]	6,0 mg 6 ml 0,60 %	1,0 mg 1 ml 0,10 %

[a] 2 ml of a 0,1 g/l tin stock solution.
[b] 5 ml of a 0,1 g/l tin stock solution.
[c] 5 ml of a 0,1 g/l lead stock solution.
[d] 2 ml of a 0,1 g/l lead stock solution.
[l] 5 ml of a 0,1 g/l manganese stock solution.
[m] 1 ml of a 0,1 g/l phosphorus stock solution.
[n] 5 ml of a 0,1 g/l phosphorus stock solution.
[o] 5 ml of a 0,1 g/l aluminium solution.

[e] 2 ml of a 0,1 g/l zinc stock solution.

[f] 5 ml of a 0,1 g/l zinc stock solution.

[g] 5 ml of a 0,1 g/l iron stock solution.

[h] 1 ml of a 0,1 g/l iron stock solution.

[i] 1 ml of a 0,1 g/l nickel stock solution.

[j] 5 ml of a 0,1 g/l nickel stock solution.

[k] 1 ml of a 0,1 g/l manganese stock solution.

[p] 2 ml of a 0,1 g/l aluminium stock solution.

[q] 5 ml of a 0,1 g/l beryllium stock solution.

[r] 1 ml of a 0,1 g/l beryllium stock solution.

[s] 1 ml of a 0,1 g/l cobalt stock solution.

[t] 5 ml of a 0,1 g/l cobalt stock solution.

[u] 1 ml of a 0,1 g/l cadmium stock solution.

[v] 5 ml of a 0,1 g/l cadmium stock solution.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

7.1.3.2 Adjustment of the apparatus

Start the inductively coupled plasma optical emission spectrometer and let it run for at least half an hour before performing any measurements.

Adjust all the instrumental parameters, each gas (outer, intermediate or central) flow rate, torch position, entrance slits, exit slits, photomultiplier tubes voltages (when appropriate), wavelengths of the analytical lines specified in Table 8, pre-spraying time and integrating time, according to the manufacturer's instructions, while aspirating (for each element) the highest concentration calibration solution.

Prepare the software for the measurement of the intensity of each analytical line and for the calculation of the corresponding mean value and relative standard deviation.

Each time the internal standard is used (Y line 371,03 nm), prepare the software to calculate the ratio between each analyte intensity and internal standard intensity.

Table 8 — Wavelengths for determinations in coppers

Element	Wavelength nm
Sn	189,90
Pb	220,30
Zn[a]	334,55
Fe	238,20
Ni	231,60
Mn	257,60
Al	308,20
P	178,23
Be	313,00
Co	228,60
Cd	226,50

[a] 206,20 nm and 213,80 nm wavelengths may be used to determine zinc, provided that interference from copper has been investigated.

7.1.3.3 Spectrometric measurements of the calibration solutions

Carry out the spectrometric measurements of the 1 g/l solutions identified P1, P2, P3 (see Table 7 and 7.1.3.1.3). For phosphorus use the 5 g/l calibration solutions (7.1.3.1.2). A simultaneous spectrometer shall be available for measurements using yttrium as "internal standard" (ratio mode).

For phosphorus determination use "absolute intensity" taking into account that "Gaussian" measuring mode may also be recommended.

For each calibration solution (including the "drift survey" solution) at least three integrations are necessary in order to calculate the mean ratioed intensities (mean absolute intensity for phosphorus).

In order to control the drift of the spectrometer, analyse the "drift survey" solution (see Table 7 and 7.1.3.1.3) at least once for every five test portion solutions. Maximum drift allowed is given in Table 9.

Table 9 — Drift survey for coppers

Element	Concentration range %	Maximum drift %
all	0,1 to 0,5	0,02

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

7.1.3.4 Calibration curves

Establish the calibration curves using measured ratioed intensities (absolute intensity for phosphorus) and corresponding analyte amounts.

Use appropriate spectrometer software for regression calculations and calculate the corresponding correlation coefficients: these coefficients should be, at least, 0,999.

7.1.4 Determination

7.1.4.1 General

The analyses shall be carried out independently, in duplicate.

7.1.4.2 Spectrometric measurement

Carry out measurements on the test solution (7.1.1.3) (7.1.1.2 for phosphorus).

Determine the contents directly using the calibration curves (7.1.3.4).

7.2 Method B: Copper-zinc alloys

7.2.1 Preparation of the test portion solution

7.2.1.1 Test portion

Weigh (1 ± 0,001) g of the test sample.

7.2.1.2 Test portion solution 5 g/l

Transfer the test portion (7.2.1.1) into a 250 ml beaker.

Add 20 ml of hydrochloric acid solution (4.2) and 5 ml of nitric acid (4.3). Cover with a watch glass and heat gently until the sample is completely dissolved, then heat to boiling point. Allow to cool.

Rinse the cover and the walls of the beaker with water.

Transfer the dissolved test portion into a 200 ml one-mark volumetric flask containing 10 ml of hydrochloric acid (4.1).

Dilute to the mark with water and mix well.

7.2.1.3 Test portion solution 1 g/l

In order to obtain solutions with 1 g/l concentration, pipette exactly 20 ml of the test portion solution (7.2.1.2) into a 100 ml one-mark volumetric flask containing 5 ml of hydrochloric acid (4.1) and 5 ml of yttrium solution (4.34). Dilute to the mark with water and mix well.

7.2.2 Check test

Make a preliminary check of the apparatus by preparing a solution of a copper-zinc reference material or a synthetic sample containing known amounts of the elements listed in Table 2 and carrying out the procedure specified in 7.2.4.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

7.2.3 Establishment of the calibration curves

7.2.3.1 Preparation of the calibration solutions

7.2.3.1.1 General

In all cases the acidity in the calibration solutions shall be similar to that of the test portion solutions.

If, for measurement purposes, a blank is required, prepare a solution containing only the same amounts of acids as in the test solution.

7.2.3.1.2 Preparation of the 5 g/l calibration solutions, using mono-elemental solutions

Weigh the quantities of copper (4.7) and zinc (4.8) shown in Table 10 and introduce them into each of a series of 250 ml beakers.

Add 20 ml of hydrochloric acid solution (4.2) and 5 ml of nitric acid (4.3) to each beaker. Cover with a watch glass and heat gently in order to dissolve the metals. Rinse the cover and the walls of the beaker with water and heat to boiling. Allow to cool and transfer each copper-zinc solution into a 200 ml one-mark volumetric flask containing 10 ml of hydrochloric acid (4.1).

Transfer the volumes of the elemental solutions of Sn, Pb, Fe, Ni, Mn, P, Al and As shown in Table 10 to each volumetric flask. Dilute to the mark with water and mix well.

7.2.3.1.3 Preparation of the 1 g/l calibration solutions

Dilute accurately the 5 g/l calibration solutions (7.2.3.1.2) in order to obtain 1 g/l calibration solutions.

Pipette exactly 20 ml of the 5 g/l calibration solutions (7.2.3.1.2) into 100 ml one-mark volumetric flasks each containing 5 ml of hydrochloric acid (4.1) and 5 ml of yttrium solution (4.34). Dilute to the mark with water and mix well.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

Table 10 — Method B — Composition of the 5 g/l calibration solutions

Element	Label				Drift survey solution
	L1	L4	L6	L7	(see 7.2.3.3)
Cu	519,8 mg	517,3 mg	768,1 mg	883,5 mg	551,0 mg
(4.7)	51,98 %	51,73 %	76,81%	88,35 %	55,10 %
Sn	0,5 mg	1,0 mg	20,0 mg	5,0 mg	10,0 mg
(4.31)		1 ml	20 ml	5 ml	10 ml
	0,05 %[a]	0,10 %	2,00 %	0,50 %	1,00 %
Pb	0,3 mg	40,0 mg	5,0 mg	1,0 mg	20,0 mg
(4.20) and (4.21)		8 ml (4.20)	5 ml (4.21)	1 ml (4.21)	4 ml (4.20)
	0,03 %[b]	4,00 %	0,50 %	0,10 %	2,00 %
Zn	420,0 mg	250,0 mg	200,0 mg	100,0 mg	320,0 mg
(4.8)	42,00 %	25,00 %	20,00 %	10,00 %	32,00 %
Fe	50,0 mg	1,0 mg	0,1 mg	5,0 mg	25,0 mg
(4.18) and (4.19)	10 ml (4.18)	1 ml (4.19)		5 ml (4.19)	5 ml (4.18)
	5,00 %	0,10 %	0,01 %[c]	0,50 %	2,50 %
Ni	0,2 mg	40,0 mg	5,0 mg	1,0 mg	20,0 mg
(4.26) and (4.27)		8 ml (4.26)	5 ml (4.27)	1 ml (4.27)	4 ml (4.26)
	0,02 %[d]	4,00 %	0,50 %	0,10 %	2,00 %
Mn	0,1 mg	60,0 mg	1 mg	2,0 mg	20,0 mg
(4.23) and (4.24)		12 ml (4.23)	1 ml (4.24)	2 ml (4.24)	4 ml (4.23)
	0,01 %[e]	6,00 %	0,10 %	0,20 %	2,00 %
P	4,0 mg	0,5 mg	0,1 mg	1,0 mg	2,0 mg
(4.28)	4 ml			1 ml	2 ml
	0,40 %[f]	0,05 %	0,01 %[g]	0,10 %	0,20 %
Al	5,0 mg	90,0 mg	0,2 mg	0,5 mg	30,0 mg
(4.9) and (4.10)	5 ml (4.10)	9 ml (4.9)			3 ml (4.9)
	0,50 %	9,00 %	0,02 %[h]	0,05 %[i]	3,00 %
As	0,1 mg	0,2 mg	0,5 mg	1,0 mg	2,0 mg
(4.12)				1 ml	2 ml
	0,01 %[j]	0,02 %[k]	0,05 %	0,10 %	0,20 %

[a] 5 ml of a 0,1 g/l tin stock solution.
[b] 3 ml of a 0,1 g/l lead stock solution.
[c] 1 ml of a 0,1 g/l iron stock solution.
[d] 2 ml of a 0,1 g/l nickel stock solution.
[e] 1 ml of a 0,1 g/l manganese stock solution.
[f] 5 ml of a 0,1 g/l phosphorus stock solution.
[g] 1 ml of a 0,1 g/l phosphorus stock solution.
[h] 2 ml of a 0,1 g/l aluminium stock solution.
[i] 1 ml of a 0,5 mg/l aluminium stock solution.
[j] 1 ml of a 0,1 g/l arsenic stock solution.
[k] 2 ml of a 0,1 g/l arsenic stock solution.
[l] 5 ml of a 0,1 g/l arsenic stock solution.

7.2.3.2 Adjustment of the apparatus

Start the inductively coupled plasma optical emission spectrometer and let it run for at least half an hour before performing any measurements.

Adjust all the instrumental parameters, each gas (outer, intermediate or central) flow rate, torch position, entrance slits, exit slits, photomultiplier tubes voltages (when appropriate), wavelengths of the analytical lines specified in Table 11, pre-spraying time and integrating time, according to the manufacturer's instructions, while aspirating (for each element) the highest concentration calibration solutions.

Prepare the software for the measurement of the intensity of each analytical line and for the calculation of the corresponding mean value and relative standard deviation.

Each time the internal standard is used (Y line 371,03 nm) prepare the software to calculate the ratio between each analyte intensity and internal standard intensity.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

Table 11 — Wavelengths for determinations in copper-zinc alloys

Element	Wavelength nm
Sn	189,90
Pb	220,30
Zn	334,55 [a]
Fe	238,20
Ni	231,60
Mn	257,60
P	178,23
Al	308,20
As	228,82 (188,98 in presence of Cd)

[a] 213,80 nm wavelength may be used to determine zinc, provided that interference from copper has been investigated.

7.2.3.3 Spectrometric measurements of the calibration solutions

Carry out the spectrometric measurements of the 1 g/l solutions identified L1, L4, L6, L7 for all the elements except zinc (see Table 10 and 7.2.3.1.2). For phosphorus and arsenic use the 5 g/l calibration solutions (7.2.3.1.3). For zinc calibration follow, as indicated hereafter:

Zinc contents between 10 % and 25 %: use L4, L6 and L7;

Zinc contents between 25 % and 42 %: use L1, L4 and L6.

A simultaneous spectrometer shall be available for measurements using yttrium as "internal standard" (ratio mode).

For phosphorus and arsenic determination, use "absolute intensity" taking into account that "Gaussian" measuring mode may also be recommended.

For each calibration solution (including the "drift survey" solution) at least three integrations are necessary in order to calculate the mean ratioed intensities (mean absolute intensity for phosphorus and arsenic).

In order to control the drift of the spectrometer, analyse the "drift survey" solution (see Table 10 and 7.2.3.1.3) at least once for every five test portion solutions. Maximum drifts allowed are given in Table 12.

Table 12 — Drift survey for copper-zinc alloys

Element	Concentration range %	Maximum drift %
all	0,5 to 2,0	0,05
	2,0 to 10,0	0,1
	10,0 to 50,0	0,2

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

7.2.3.4 Calibration curves

Establish the calibration curves using measured ratioed intensities (absolute intensity for phosphorus and arsenic) and corresponding analyte amounts.

Use appropriate spectrometer software for regression calculations and calculate the corresponding correlation coefficients: these coefficients should be, at least, 0,999.

7.2.4 Determination

7.2.4.1 General

The analyses shall be carried out independently, in duplicate.

7.2.4.2 Spectrometric measurement

Carry out measurements on the test solution (7.2.1.3) (7.2.1.2 for phosphorus and arsenic).

Determine the contents directly using the calibration curves (7.2.3.4).

7.3 Method C: Copper-tin alloys

7.3.1 Preparation of the test portion solution

7.3.1.1 Test portion

Weigh (1 ± 0,001) g of the test sample.

7.3.1.2 Test portion solution 5 g/l

Transfer the test portion (7.3.1.1) into a 250 ml beaker.

Add 20 ml of hydrochloric acid solution (4.2) and 5 ml of nitric acid (4.3). Cover with a watch glass and heat gently until the sample is completely dissolved, then heat to boiling. Allow to cool. Rinse the cover and the walls of the beaker with water.

Transfer the dissolved test portion into a 200 ml one-mark volumetric flask containing 10 ml of hydrochloric acid (4.1).

Dilute to the mark with water and mix well.

7.3.1.3 Test portion solution 1 g/l

In order to obtain solutions with 1 g/l concentration, pipette exactly 20 ml of the test portion solution (7.3.1.2) into a 100 ml one-mark volumetric flask containing 5 ml of hydrochloric acid (4.1) and 5 ml of yttrium solution (4.34). Dilute to the mark with water and mix well.

7.3.2 Check test

Make a preliminary check of the apparatus by preparing a solution of a copper-tin reference material or a synthetic sample containing known amounts of the elements listed in Table 3 and carrying out the procedure specified in 7.3.4.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

7.3.3 Establishment of the calibration curves

7.3.3.1 Preparation of the calibration solutions

7.3.3.1.1 General

In all cases the acidity of the calibration solutions shall be similar to that of the test portion solutions.

If, for measurement purposes, a blank is required, prepare a solution containing only the same amounts of acids as in the test solution.

7.3.3.1.2 Preparation of the 5 g/l calibration solutions, using mono-elemental solutions

Weigh the quantities of copper (4.7) shown in Table 13 and introduce them into each of a series of 250 ml beakers.

Add 20 ml of hydrochloric acid solution (4.2) and 5 ml of nitric acid (4.3) to each beaker. Cover with a watch glass and heat gently in order to dissolve the copper. Rinse the cover and the walls of the beaker with water and heat to boiling. Allow to cool and transfer each copper solution into a 200 ml one-mark volumetric flask containing 10 ml of hydrochloric acid (4.1).

Transfer the volumes of the elemental solutions of Sn, Pb, Zn, Fe, Ni, Mn, P, Sb, Al and As shown in Table 13 to each volumetric flask. Dilute to the mark with water and mix well.

7.3.3.1.3 Preparation of the 1 g/l calibration solutions

Dilute accurately the 5 g/l calibration solutions (7.3.3.1.2) in order to obtain 1 g/l calibration solutions.

Pipette exactly 20 ml of the 5 g/l calibration solutions (7.3.1.2) into a 100 ml one-mark volumetric flasks each containing 5 ml of hydrochloric acid (4.1) and 5 ml of yttrium solution (4.34). Dilute to the mark with water and mix well.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

Table 13 — Method C — Composition of the 5 g/l calibration solutions

Element	Label			Drift survey solution
	E1	E5	E8	(see 7.3.3.3)
Cu	739,9 mg	902,5 mg	804,9 mg	777,0 mg
(4.7)	73,99 %	90,25 %	80,49 %	77,70 %
Sn	160,0 mg	90,0 mg	30,0 mg	120,0 mg
(4.29)	16 ml	9 ml	3 ml	12 ml
	16,00 %	9,00 %	3,00 %	12,00 %
Pb	0,1 mg	1,0 mg	90,0 mg	40,0 mg
(4.20) and (4.21)		1 ml (4.21)	18 ml (4.20)	8 ml (4.20)
	[a]			
	0,01 %	0,10 %	9,00 %	4,00 %
Zn	0,3 mg	1,0 mg	60,0 mg	20,0 mg
(4.32) and (4.33)		1 ml (4.33)	6 ml (4.32)	20 ml (4.33)
	[b]			
	0,03 %	0,10 %	6,00 %	2,00 %
Fe	0,1 mg	1,0 mg	10,0 mg	2,0 mg
(4.19)		1 ml	10 ml	2 ml
	[c]			
	0,01 %	0,10 %	1,00 %	0,20 %
Ni	70,0 mg	1,0 mg	0,5 mg	30,0 mg
(4.26) and (4.27)	14 ml (4.26)	1 ml (4.27)		6 ml (4.26)
			[d]	
	7,00 %	0,10 %	0,05 %	3,00 %
P	6,0 mg	1,0 mg	0,1 mg	2,0 mg
(4.28)	6 ml	1 ml		2 ml
			[e]	
	0,60 %	0,10 %	0,01 %	0,20 %
Sb	16,0 mg	1,0 mg	0,2 mg	5,0 mg
(4.11)	16 ml	1 ml		5 ml
			[f]	
	1,60 %	0,10 %	0,02 %	0,50 %
Mn	0,1 mg	0,5 mg	4,0 mg	1,0 mg
(4.24)			4 ml	1 ml
	[g]	[h]		
	0,01 %	0,05 %	0,40 %	0,10 %
Al	5,0 mg	0,5 mg	0,1 mg	2,0 mg
(4.10)	5 ml			2 ml
		[i]	[j]	
	0,50 %	0,05 %	0,01 %	0,20 %
As	2,5 mg	0,5 mg	0,2 mg	1,0 mg
(4.12)	2,5 ml			1 ml
		[k]	[l]	
	0,25 %	0,05 %	0,02 %	0,10 %

[a] 1 ml of a 0,1 g/l lead stock solution.
[b] 3 ml of a 0,1 g/l zinc stock solution.
[c] 1 ml of a 0,1 g/l iron stock solution.
[d] 5 ml of a 0,1 g/l nickel stock solution.
[e] 1 ml of a 0,1 g/l phosphorus stock solution.
[f] 2 ml of a 0,1 g/l antimony stock solution.
[g] 1 ml of a 0,1 g/l manganese stock solution
[h] 5 ml of a 0,1 g/l manganese stock solution
[i] 5 ml of a 0,1 g/l aluminium stock solution
[j] 1 ml of a 0,1 g/l aluminium stock solution
[k] 5 ml of a 0,1 g/l arsenic stock solution
[l] 1 ml of a 0,1 g/l arsenic stock solution

7.3.3.2 Adjustment of the apparatus

Start the inductively coupled plasma optical emission spectrometer and let it run for at least half an hour before performing any measurements.

Adjust all the instrumental parameters, each gas (outer, intermediate or central) flow rate, torch position, entrance slits, exit slits, photomultiplier tubes voltages (when appropriate), wavelengths of the analytical lines specified in Table 14, pre-spraying time and integrating time, according to the manufacturer's instructions, while aspirating (for each element) the highest concentration calibration solutions.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

Prepare the software for the measurement of the intensity of each analytical line and for the calculation of the corresponding mean value and relative standard deviation.

Each time the internal standard is used (Y line 371,03 nm) prepare the software to calculate the ratio between each analyte intensity and internal standard intensity.

Table 14 — Wavelengths for determinations in copper-tin alloys

Element	Wavelength nm
Sn	189,90
Pb	220,30
Zn	334,55 [a]
Fe	238,20
Ni	231,60
Mn	257,60
Al	308,20
P	178,23
Sb	206,80
As	228,82 (188,98 in presence of Cd)

[a] 213,80 nm wavelength may be used to determine zinc, provided that interference from copper has been investigated.

7.3.3.3 Spectrometric measurements of the calibration solutions

Carry out the spectrometric measurements of the 1 g/l solutions identified E1, E5, E8 (see Table 13 and 7.3.3.1.3). For phosphorus and arsenic use the 5 g/l calibration solutions (7.3.3.1.2).

A simultaneous spectrometer shall be available for measurements using yttrium as "internal standard" (ratio mode).

For phosphorus and arsenic determination use "absolute intensity" taking into account that "Gaussian" measuring mode may also be recommended.

For each calibration solution (including the "drift survey" solution) at least three integrations are necessary in order to calculate the mean ratioed intensities (mean absolute intensity for phosphorus and arsenic).

In order to control the drift of the spectrometer, analyse the "drift survey" solution (see Table 13 and 7.3.3.1.3) at least once for every five test portion solutions. Maximum drifts allowed are given in Table 15.

Table 15 — Drift survey for copper-tin alloys

Element	Concentration range **drift** %	Maximum %
all	0,1 to 0,5	0,02
	0,5 to 2,0	0,05
	2,0 to 10,0	0,1
	10,0 to 50,0	0,2

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

7.3.3.4 Calibration curves

Establish the calibration curves using measured ratioed intensities (absolute intensity for phosphorus and arsenic) and corresponding analyte amounts.

Use appropriate spectrometer software for regression calculations and calculate the corresponding correlation coefficients: these coefficients should be, at least, 0,999.

7.3.4 Determination

7.3.4.1 General

The analyses shall be carried out independently, in duplicate.

7.3.4.2 Spectrometric measurement

Carry out measurements on the test solution (7.3.1.3) (7.3.1.2 for phosphorus and arsenic).

Determine the contents directly using the calibration curves (7.3.3.4).

7.4 Method D: Copper-aluminium alloys

7.4.1 Preparation of the test portion solution

7.4.1.1 Test portion

Weigh (1 ± 0,001) g of the test sample.

7.4.1.2 Test portion solution 5 g/l

Transfer the test portion (7.4.1.1) into a 250 ml beaker.

Add 20 ml of hydrochloric acid solution (4.2) and 5 ml of nitric acid (4.3). Cover with a watch glass and heat gently until the sample is completely dissolved, then heat to boiling. Allow to cool.

Rinse the cover and the walls of the beaker with water.

Transfer the dissolved test portion into a 200 ml one-mark volumetric flask containing 10 ml of hydrochloric acid (4.1).

Dilute to the mark with water and mix well.

7.4.1.3 Test portion solution 1 g/l

In order to obtain solutions with 1 g/l concentration, pipette exactly 20 ml of the test portion solution (7.4.1.2) into a 100 ml one-mark volumetric flask containing 5 ml of hydrochloric acid (4.1) and 5 ml of yttrium solution (4.34). Dilute to the mark with water and mix well.

7.4.2 Check test

Make a preliminary check of the apparatus by preparing a solution of a copper-aluminium alloy reference material or a synthetic sample containing known amounts of the elements listed in Table 4 and carrying out the procedure specified in 7.4.4.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

7.4.3 Establishment of the calibration curves

7.4.3.1 Preparation of the calibration solutions

7.4.3.1.1 General

In all cases the acidity of the calibration solutions shall be similar to that of the test portion solutions.

If, for measurement purposes, a blank is required, prepare a solution containing only the same amounts of acids as in the test solution.

7.4.3.1.2 Preparation of the 5 g/l calibration solutions, using mono-elemental solutions

Weigh the quantities of copper (4.7) shown in Table 16 and introduce them into each of a series of 250 ml beakers.

Add 20 ml of hydrochloric acid solution (4.2) and 5 ml of nitric acid (4.3) to each beaker. Cover with a watch glass and heat gently in order to dissolve the copper. Rinse the cover and the walls of the beaker with water and heat to boiling. Allow to cool and transfer each copper solution into a 200 ml one-mark volumetric flask containing 10 ml of hydrochloric acid (4.1).

Transfer the volumes of the elemental solutions of Sn, Pb, Zn, Fe, Ni, Mn, Al, Cd and Mg shown in Table 16 to each volumetric flask. Dilute to the mark with water and mix well.

7.4.3.1.3 Preparation of the 1 g/l calibration solutions

Dilute accurately the 5 g/l calibration solutions (7.4.3.1.2) in order to obtain 1 g/l calibration solutions.

Pipette exactly 20 ml of the 5 g/l calibration solutions (7.4.3.1.2) into 100 ml one-mark volumetric flasks each containing 5 ml of hydrochloric acid (4.1) and 5 ml of yttrium solution (4.34). Dilute to the mark with water and mix well.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

Table 16 — Method D — Composition of the 5 g/l calibration solutions

Element	Label			Drift survey solution
	C1	C3	C6	
				(see 7.4.3.3)
Cu	756,5 mg	787,4 mg	909,0 mg	805,5 mg
(4.7)	75,65 %	78,74 %	90,90 %	80,55 %
Sn	0,5mg	0,2 mg	5,0 mg	1,0 mg
(4.31)	5 ml	1 ml		
	a	b		
Pb	0,05 %	0,02 %	0,50 %	0,10 %
	5,0 mg	0,3 mg	0,5mg	1,0 mg
(4.21)	5 ml	1 ml		
		c	d	
Zn	0,50 %	0,03 %	0,05 %	0,10 %
	10,0 mg	0,5 mg	0,3mg	1,0 mg
(4.33)	10 ml	1 ml		
		e	f	
Fe	1,00 %	0,05 %	0,03 %	0,10 %
	0,5mg	70,0 mg	5,0 mg	30,0 mg
(4.18) and (4.19)		14 ml (4.18)	5 ml (4.19)	6 ml (4.18)
	g			
	0,05 %	7,00 %	0,50 %	3,00 %
Ni	80,0 mg	1,0 mg	20,0 mg	40,0 mg
(4.25), (4.26) and (4.27)	8 ml (4.25)	1 ml (4.28)	4 ml (4.26)	8 ml (4.26)
	8,00 %	0,10 %	2,00 %	4,00 %
Mn	1,0 mg	50,0 mg	0,1 mg	10,0 mg
(4.23) and (4.24)	1 ml (4.24)	10 ml (4.23)	h	10 ml (4.24)
	0,10 %	5,00 %	0,01 %	1,00 %
	140,0 mg	90,0 mg	60,0 mg	110,0 mg
Al	14 ml	9 ml	6 ml	11 ml
(4.9)	14,00 %	9,00 %	6,00 %	11,00 %
Cd	5,0 mg	0,5 mg	0,1 mg	1,0 mg
(4.15)	5 ml	i	j	1 ml
	0,50 %	0,05 %	0,01 %	0,10 %
Mg	1,5 mg	0,1 mg	0,02 mg	0,5 mg
(4.22)	k	l	m	n

0,15 %	0,01 %	0,002 %	0,05 %

[a] 5 ml of a 0,1 g/l tin stock solution.

[b] 2 ml of a 0,1 g/l tin stock solution.

[c] 3 ml of a 0,1 g/l lead stock solution.

[d] 5 ml of a 0,1 g/l lead stock solution.

[e] 5 ml of a 0,1 g/l zinc stock solution.

[f] 3 ml of a 0,1 g/l zinc stock solution.

[g] 5 ml of a 0,1 g/l iron stock solution.

[h] 1 ml of a 0,1 g/l manganese stock solution.

[i] 5 ml of a 0,1 g/l cadmium stock solution.

[j] 1 ml of a 0,1 g/l cadmium stock solution.

[k] 15 ml of a 0,1 g/l magnesium stock solution.

[l] 1 ml of a 0,1 g/l magnesium stock solution.

[m] 2 ml of a 0,01 g/l magnesium stock solution.

[n] 5 ml of a 0,1 g/l magnesium stock solution.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

7.4.3.2 Adjustment of the apparatus

Start the inductively coupled plasma optical emission spectrometer and let it run for at least half an hour before performing any measurements.

Adjust all the instrumental parameters, each gas (outer, intermediate or central) flow rate, torch position, entrance slits, exit slits, photomultiplier tubes voltages (when appropriate), wavelengths of the analytical lines specified in Table 17, pre-spraying time and integrating time, according to the manufacturer's instructions, while aspirating (for each element) the highest concentration calibration solutions.

Prepare the software for the measurement of the intensity of each analytical line and for the calculation of the corresponding mean value and relative standard deviation.

Each time the internal standard is used (Y line 371,03 nm), prepare the software to calculate the ratio between each analyte intensity and internal standard intensity.

Table 17 — Wavelengths for determinations in copper-aluminium alloys

Element	Wavelength nm
Sn	189,90
Pb	220,30
Zn	334,55 [a]
Fe	238,20
Ni	231,60
Mn	257,60
Al	308,20
Cd	266,50
Mg	279,55

[a] 213,80 nm wavelength may be used to determine zinc, provided that interference from copper has been investigated.

7.4.3.3 Spectrometric measurements of the calibration solutions

Carry out the spectrometric measurements of the 1 g/l solutions identified C1, C3, C6 (see Table 16 and 7.4.3.1.3). For magnesium use the 5 g/l calibration solutions (7.4.3.1.2).

A simultaneous spectrometer shall be available for measurements using yttrium as "internal standard" (ratio mode).

For magnesium determination use "absolute intensity" taking into account that "Gaussian" measuring mode may also be recommended.

For each calibration solution (including the "drift survey" solution) at least three integrations are necessary in order to calculate the mean ratioed intensities (mean absolute intensity for magnesium).

In order to control the drift of the spectrometer, analyse the "drift survey" solution (see Table 16 and 7.4.3.1.3) at least once for every five test portion solutions. Maximum drifts allowed are given in Table 18.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

Table 18 — Drift survey for copper–aluminium alloys

Element	Concentration range %	Maximum drift %
all	0,1 to 0,5	0,02
	0,5 to 2,0	0,05
	2,0 to 10,0	0,1

7.4.3.4 Calibration curves

Establish the calibration curves using measured ratioed intensities (absolute intensity for magnesium) and corresponding analyte amounts.

Use appropriate spectrometer software for regression calculations and calculate the corresponding correlation coefficients: these coefficients should be, at least, 0,999.

7.4.4 Determination

7.4.4.1 General

The analyses shall be carried out independently, in duplicate.

7.4.4.2 Spectrometric measurement

Carry out measurements on the test solution (7.4.1.3) (7.4.1.2 for magnesium).

Determine the contents directly using the calibration curves (7.4.3.4).

7.5 Method E: Copper-beryllium alloys

7.5.1 Preparation of the test portion solution

7.5.1.1 Test portion

Weigh (1 ± 0,001) g of the test sample.

7.5.1.2 Test portion solution 5 g/l

Transfer the test portion (7.5.1.1) into a 250 ml beaker.

Add 20 ml of hydrochloric acid solution (4.2) and 5 ml of nitric acid (4.3). Cover with a watch glass and heat gently until the sample is completely dissolved, then heat to boiling. Allow to cool. Rinse the cover and the walls of the beaker with water.

Transfer the dissolved test portion into a 200 ml one-mark volumetric flask containing 10 ml of hydrochloric acid (4.1). Dilute to the mark with water and mix well.

7.5.1.3 Test portion solution 1 g/l

In order to obtain solutions with 1 g/l concentration, pipette exactly 20 ml of the test portion solution (7.5.1.2) into a 100 ml one-mark volumetric flask containing 5 ml of hydrochloric acid (4.1) and 5 ml of yttrium solution (4.34). Dilute to the mark with water and mix well.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

7.5.2 Check test

Make a preliminary check of the apparatus by preparing a solution of a copper-beryllium alloy reference material, or a synthetic sample containing known amounts of the elements listed in Table 5 and carrying out the procedure specified in 7.5.4.

7.5.3 Establishment of the calibration curves

7.5.3.1 Preparation of the calibration solutions

7.5.3.1.1 General

In all cases the acidity of the calibration solutions shall be similar to that of the test portion solutions.

If, for measurement purposes, a blank is required, prepare a solution containing only the same amounts of acids as in the test solution.

7.5.3.1.2 Preparation of the 5 g/l calibration solutions, using mono-elemental solutions

Weigh the quantities of copper (4.7) shown in Table 19 and introduce them into each of a series of 250 ml beakers.

Add 20 ml of hydrochloric acid solution (4.2) and 5 ml of nitric acid (4.3) to each beaker. Cover with a watch glass and heat gently in order to dissolve the copper. Rinse the cover and the walls of the beaker with water and heat to boiling. Allow to cool and transfer each copper solution into a 200 ml one-mark volumetric flask containing 10 ml of hydrochloric acid (4.1).

Transfer the volumes of the elemental solutions of Sn, Pb, Zn, Fe, Ni, Mn, Al, Be and Co shown in Table 19 to each volumetric flask. Dilute to the mark with water and mix well.

7.5.3.1.3 Preparation of the 1 g/l calibration solutions

Dilute accurately the 5 g/l calibration solutions (7.5.3.1.2) in order to obtain 1 g/l calibration solutions.

Pipette exactly 20 ml of the 5 g/l calibration solutions (7.5.3.1.2) into 100 ml one-mark volumetric flasks each containing 5 ml of hydrochloric acid (4.1) and 5 ml of yttrium solution (4.34). Dilute to the mark with water and mix well.

Provided by IHS
Not for Resale

No reproduction or networking permitted without license from IHS

Table 19 — Method E — Composition of the 5 g/l calibration solutions

Element	Label			Drift survey solution
	B1	B3	B5	(see 7.5.3.3)
Cu (4.7) Sn (4.31)	951,3 mg 95,13 % 0,2 mg	993,4 mg 99,34 % 0,5 mg	928,5 mg 92,85 % 2,0 mg 2 ml	944,5 mg 94,45 % 1,0 mg 1 ml
Pb (4.21)	[a] 0,02 % 2,0 mg 2 ml	[b] 0,05 % 0,4 mg	0,20 % 0,1 mg	0,10 % 1,0 mg 1 ml
Zn (4.33)	0,20 % 0,3 mg	[c] 0,04 % 0,5 mg	[d] 0,01 % 2,0 mg 2 ml	0,10 % 1,0 mg 1 ml
Fe (4.19)	[e] 0,03 % 3,0 mg 3 ml	[f] 0,05 % 0,6 mg	0,20 % 0,3 mg	0,10 % 1,0 mg 1 ml
Ni (4.27)	0,30 %	[g] 0,06 %	[h] 0,03 %	0,10 %
Mn (4.24)	0,4 mg	1,0 mg 1 ml	25,0 mg 25 ml	10,0 mg 10 ml
Al (4.10)	[i] 0,04 % 0,06 mg	0,10 % 0,1 mg	2,50 % 1,5 mg	1,00 % 0,5 mg
Be (4.13) and (4.14)	[j] 0,006 % 2,0 mg 2 ml	[k] 0,01 % 0,5 mg	[l] 0,15 % 0,3 mg	[m] 0,05 % 1,0 mg 1 ml
Co (4.16) and (4.17)	0,20 % 0,8 mg	[n] 0,05 % 2,0 mg 2 ml (4.14)	[o] 0,03 % 40,0 mg 8 ml (4.13)	0,10 % 20,0 mg 4 ml (4.13)
	[p] 0,08 % 40,0 mg 8 ml (4.16)	0,20 % 1,0 mg 1 ml (4.17)	4,00 % 0,3 mg	2,00 % 20,0 mg 4 ml (4.16)
	4,00 %	0,10 %	[q] 0,03 %	2,00 %

[a] 2 ml of a 0,1 g/l tin stock solution.
[b] 5 ml of a 0,1 g/l tin stock solution.
[c] 4 ml of a 0,1 g/l lead stock solution.
[d] 1 ml of a 0,1 g/l lead stock solution.
[e] 3 ml of a 0,1 g/l zinc stock solution.
[f] 5 ml of a 0,1 g/l zinc stock solution.
[g] 6 ml of a 0,1 g/l iron stock solution.
[h] 3 ml of a 0,1 g/l iron stock solution.
[i] 4 ml of a 0,1 g/l nickel stock solution.
[j] 6 ml of a 0,01 g/l manganese stock solution.
[k] 1 ml of a 0,1 g/l manganese stock solution.
[l] 15 ml of a 0,1 g/l manganese stock solution.
[m] 5 ml of a 0,1 g/l manganese stock solution.
[n] 5 ml of a 0,1 g/l aluminium stock solution.
[o] 3 ml of a 0,1 g/l aluminium stock solution.
[p] 8 ml of a 0,1 g/l beryllium stock solution.
[q] 3 ml of a 0,1 g/l cobalt stock solution.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

7.5.3.2 Adjustment of the apparatus

Start the inductively coupled plasma optical emission spectrometer and let it run for at least half an hour before performing any measurements.

Adjust all the instrumental parameters, each gas (outer, intermediate or central) flow rate, torch position, entrance slits, exit slits, photomultiplier tubes voltages (when appropriate), wavelengths of the analytical lines specified in Table 20, pre-spraying time and integrating time, according to the manufacturer's instructions, while aspirating (for each element) the highest concentration calibration solutions.

Prepare the software for the measurement of the intensity of each analytical line and for the calculation of the corresponding mean value and relative standard deviation.

Each time the internal standard is used (Y line 371,03 nm) prepare the software to calculate the ratio between each analyte intensity and internal standard intensity.

Table 20 — Wavelengths for determinations in copper-beryllium alloys

Element	Wavelength nm
Sn	189,90
Pb	220,30
Zn	334,55 [a]
Fe	238,20
Ni	231,60
Mn	257,60
Al	308,20
Be	313,00
Co	228,60

[a] 213,80 nm wavelength may be used to determine zinc, provided that interference from Copper has been investigated.

7.5.3.3 Spectrometric measurements of the calibration solutions

Carry out the spectrometric measurements of the 1 g/l solutions identified B1, B3, B5 (see Table 19 and 7.5.3.1.3). A simultaneous spectrometer shall be available for measurements using yttrium as "internal standard" (ratio mode).

For each calibration solution (including the "drift survey" solution) at least three integrations are necessary in order to calculate the mean ratioed intensities.

In order to control the drift of the spectrometer, analyse the "drift survey" solution (see Table 19 and 7.5.3.1.3) at least once for every five test portion solutions. Maximum drifts allowed are given in Table 21.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

Table 21 — Drift survey for copper-beryllium alloys

Element	Concentration range %	Maximum drift %
all	0,1 to 0,5	0,02
	0,5 to 2,0	0,05
	2,0 to 10,0	0,1

7.5.3.4 Calibration curves

Establish the calibration curves using measured mean ratioed intensities and corresponding analyte amounts.

Use appropriate spectrometer software for regression calculations and calculate the corresponding correlation coefficients: these coefficients should be, at least, 0,999.

7.5.4 Determination

7.5.4.1 General

The analyses shall be carried out independently, in duplicate.

7.5.4.2 Spectrometric measurement

Carry out measurements on the test solution (7.5.1.3).

Determine the contents directly using the calibration curves (7.5.3.4).

7.6 Method F: Copper-nickel alloys

7.6.1 Preparation of the test portion solution

7.6.1.1 Test portion

Weigh (1 ± 0,001) g of the test sample.

7.6.1.2 Test portion solution 5 g/l

Transfer the test portion (7.6.1.1) into a 250 ml beaker.

Add 20 ml of hydrochloric acid solution (4.2) and 5 ml of nitric acid (4.3). Cover with a watch glass and heat gently.

In the cases where samples are completely dissolved (absence of free carbon, namely) add about 40 ml of water, then heat to boiling. Allow to cool. Rinse the cover and the walls of the beaker with water. Transfer the dissolved test portion into a 200 ml one-mark volumetric flask containing 10 ml of hydrochloric acid (4.1). Dilute to the mark with water and mix well.

In the cases where a residue is observed (namely, presence of free carbon) add about 40 ml of water, then heat to boiling. Allow to cool. Filter the solution through a dense-texture filter-paper. Transfer the filtrate to a 200 ml one-mark volumetric flask. Rinse the beaker cover, the walls of the beaker and the filter with water. Combine all the washings with the main solution.

Introduce the filter and its contents into a platinum crucible. Heat at 950 °C for 15 min.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

Allow to cool, add 1 ml of nitric acid (4.3) and 1 ml of hydrofluoric acid (4.5) to the crucible, heat carefully to dryness. Add to the crucible 10 ml of hydrochloric acid (4.1) and heat very gently until a clear solution is obtained. Combine this solution with the main solution. Dilute to the mark with water and mix well.

7.6.1.3 Test portion solution 1 g/l

In order to obtain solutions with 1 g/l concentration, pipette exactly 20 ml of the test portion solution (7.6.1.2) into a 100 ml one-mark volumetric flask containing 5 ml of hydrochloric acid (4.1) and 5 ml of yttrium solution (4.34). Dilute to the mark with water and mix well.

7.6.2 Check test

Make a preliminary check of the apparatus by preparing a solution of a copper-nickel alloy reference material or a synthetic sample containing known amounts of the elements listed in Table 6 and carrying out the procedure specified in 7.6.4.

7.6.3 Establishment of the calibration curves

7.6.3.1 Preparation of the calibration solutions

7.6.3.1.1 General

In all cases the acidity of the calibration solutions shall be similar to that of the test portion solutions.

If, for measurement purposes, a blank is required, prepare a solution containing only the same amounts of acids as in the test solution.

7.6.3.1.2 Preparation of the 5 g/l calibration solutions, using mono-elemental solutions

Weigh the quantities of copper (4.7) shown in Table 22 and introduce them into each of a series of 250 ml beakers.

Add 20 ml of hydrochloric acid solution (4.2) and 5 ml of nitric acid (4.3) to each beaker. Cover with a watch glass and heat gently in order to dissolve the copper. Rinse the cover and the walls of the beaker with water and heat to boiling. Allow to cool and transfer each copper solution into a 200 ml one-mark volumetric flask containing 10 ml of hydrochloric acid (4.1).

Transfer the volumes of the elemental solutions of Sn, Pb, Zn, Fe, Ni, Mn and Al shown in Table 22 to each volumetric flask. Dilute to the mark with water and mix well.

7.6.3.1.3 Preparation of the 1 g/l calibration solutions

Dilute accurately the 5 g/l calibration solutions (7.6.3.1.2) in order to obtain 1 g/l calibration solutions.

Pipette exactly 20 ml of the 5 g/l calibration solutions (7.6.3.1.2) into 100 ml one-mark volumetric flasks each containing 5 ml of hydrochloric acid (4.1) and 5 ml of yttrium solution (4.34). Dilute to the mark with water and mix well.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

Table 22 — Method F — Composition of the 5 g/l calibration solutions

Element	Label			Drift survey solution
	N1	N3	N5	(see 7.6.3.3)
Cu (4.7)	593,5 mg 59,35 %	792,3 mg 79,23 %	879,1 mg 87,91 %	694,0 mg 69,40 %
Sn (4.31)	5,0 mg 5 ml	0,6 mg	0,3 mg	2,0 mg 2 ml
Pb (4.21)	0,50 % 0,3mg	0,06 %[a] 0,6 mg	0,03 %[b] 5,0 mg 5 ml	0,20 % 2,0 mg 2 ml
Zn (4.33)	0,03 %[c] 20,0 mg 20 ml	0,06 %[d] 1,0 mg 1 ml	0,50 % 0,4 mg	0,20 % 10,0 mg 10 ml
Fe (4.18) and (4.19)	2,00 % 1,0 mg 1 ml (4.19)	0,10 % 4,0 mg 4 ml (4.19)	0,04 %[e] 40,0 mg 8 ml (4.18)	1,00 % 20,0 mg 4 ml (4.18)
Ni (4.25)	0,10 % 350,0 mg 35 ml	0,40 % 200,0 mg 20 ml	4,00 % 70,0 mg 7 ml	2,00 % 250,0 mg 25 ml
Mn (4.23) and (4.24)	35,00 % 30,0 mg 6 ml (4.23)	20,00 % 1,0 mg 1 ml (4.24)	7,00 % 0,2 mg	25,00 % 20,0 mg 4 ml (4.23)
Al (4.10)	3,00 % 0,2 mg	0,10 % 0,5 mg	0,02 %[f] 5,0 mg 5 ml	2,00 % 2,0 mg 2 ml
	0,02 %[g]	0,05 %[h]	0,50 %	0,20 %

[a] 6 ml of a 0,1 g/l tin stock solution.
[b] 3 ml of a 0,1 g/l tin stock solution.
[c] 3 ml of a 0,1 g/l lead stock solution.
[d] 6 ml of a 0,1 g/l lead stock solution.
[e] 4 ml of a 0,1 g/l zinc stock solution.
[f] 2 ml of a 0,1 g/l manganese stock solution.
[g] 2 ml of a 0,1 g/l aluminium stock solution.
[h] 5 ml of a 0,1 g/l aluminium stock solution.

7.6.3.2 Adjustment of the apparatus

Start the inductively coupled plasma optical emission spectrometer and let it run for at least half an hour before performing any measurements.

Adjust all the instrumental parameters, each gas (outer, intermediate or central) flow rate, torch position, entrance slits, exit slits, photomultiplier tubes voltages (when appropriate), wavelengths of the analytical lines specified in Table 23, pre-spraying time and integrating time, according to the manufacturer's instructions, while aspirating (for each element) the highest concentration calibration solutions.

Prepare the software for the measurement of the intensity of each analytical line and for the calculation of the corresponding mean value and relative standard deviation.

Each time the internal standard is used (Y line 371,03 nm), prepare the software to calculate the ratio between each analyte intensity and internal standard intensity.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

Table 23 — Wavelengths for determination in copper-nickel alloys

Element	Wavelength nm
Sn	189,90
Pb	220,30
Zn	334,55 [a]
Fe	238,20
Ni	231,60
Mn	257,60
Al	308,20

[a] 213,80 nm wavelength may be used to determine zinc, provided that interference from copper has been investigated.

7.6.3.3 Spectrometric measurements of the calibration solutions

Carry out the spectrometric measurements of the 1 g/l solutions identified N1, N3, N5 (see Table 22 and 7.6.3.1.3). A simultaneous spectrometer shall be available for measurements using yttrium as "internal standard" (ratio mode).

For each calibration solution (including the "drift survey" solution) at least three integrations are necessary in order to calculate the mean ratioed intensities.

In order to control the drift of the spectrometer, analyse the "drift survey" solution (see Table 22 and 7.6.3.1.3) at least once for every five test portions solutions. Maximum drifts allowed are given in Table 24.

Table 24 — Method F — Drift survey for copper-nickel alloys

Element	Concentration range %	Maximum drift %
all	0,1 to 0,5	0,02
	0,5 to 2,0	0,05
	2,0 to 10,0	0,1
	10,0 to 50,0	0,2

7.6.3.4 Calibration curves

Establish the calibration curves using measured ratioed intensities and corresponding analyte amounts.

Use appropriate spectrometer software for regression calculations and calculate the corresponding correlation coefficients: these coefficients should be, at least, 0,999.

7.6.4 Determination

7.6.4.1 General

The analyses shall be carried out independently, in duplicate.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

7.6.4.2 Spectrometric measurement

Carry out measurements on the test solution (7.6.1.3).

Determine the contents directly using the calibration curves (7.6.3.4).

8 Expression of results

The calibration curves are drawn from the measurements carried out either in the "ratio" or in "intensity" mode according to the concentrations of the various elements. On the calibration curves, read the contents, expressed as mass fraction in percent of the elements determined in the test sample.

9 Precision

9.1 Method A — Coppers

Five laboratories co-operated in validating this method and obtained the results summarized in Table 25.

Table 25 — Method A — Statistical information

Element	Reference value %	Found %	Repeatability r	Reproducibility R
Sn	0,024 7	0,024 2	0,002 8	0,003 0
Pb	0,023 6	0,023 9	0,002 8	0,003 4
Zn	0,021 7	0,021 6	0,001 4	0,001 5
Fe	0,023 5	0,023 1	0,001 8	0,003 7
Ni	0,020 9	0,020 8	0,001 2	0,001 5
Mn	0,020 6	0,020 2	0,000 5	0,001 1
P	0,020 3	0,020 5	0,001 7	0,002 3
Co	0,020 8	0,020 8	0,001 0	0,001 3
Cd	0,018 6	0,018 6	0,000 8	0,001 3

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

9.2 Method B — Copper-zinc alloys

Eight laboratories co-operated in validating this method and obtained the results summarized in Table 26.

Table 26 — Method B — Statistical information

Element	Reference value %	Found %	Repeatability r	Reproducibility R
Sn	0,209	0,208 0	0,015 0	0,022 4
	0,27	0,254 0	0,014 2	0,016 7
	0,70	0,692 4	0,040 1	0,051 5
Pb	0,35	0,353 0	0,009 9	0,024 2
	2,24	2,253 1	0,055 0	0,154 8
	2,90	2,867 6	0,055 6	0,164 2
Zn	35,8	35,983 4	0,620 9	0,648 0
	38,02	38,440 0	0,676 6	1,031 9
Fe	0,15	0,146 0	0,011 6	0,025 6
	0,207	0,206 7	0,014 6	0,026 6
	1,02	1,013 0	0,038 7	0,100 2
Ni	0,105	0,102 3	0,003 9	0,010 3
	0,13	0,126 5	0,004 6	0,013 9
	0,56	0,554 5	0,019 6	0,043 9
Mn	0,022 2	0,020 3	0,002 2	0,006 6
	0,86	0,878 4	0,035 9	0,075 3
Al	0,027	0,026 7	0,004 8	0,007 3
	2,22	2,238 7	0,028 0	0,078 3
As	0,023 1	0,022 5	0,001 5	0,005 1

NOTE For Zinc, it was decided to remove the precision data corresponding to the sample BCS 385 (38,5 % content level), as it was assumed that this sample may not be enough homogeneous regarding to its Zinc content

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

9.3 Method C — Copper-tin alloys

Seven laboratories co-operated in validating this method and obtained the results summarized in Table 27.

Table 27 — Method C — Statistical information

Element	Reference value %	Found %	Repeatability r	Reproducibility R
Sn	5,21	5,211 1	0,059 0	0,081 1
	7,27	7,290 2	0,103 3	0,145 0
Pb	3,15	3,163 3	0,090 6	0,119 8
	5,11	5,210 8	0,062 6	0,131 4
Zn	3,47	3,528 3	0,135 4	≤ *r*
	5,07	5,156 7	0,094 3	0,124 5
Fe	0,056	0,051 7	0,002 0	0,006 4
Ni	1,10	1,100 1	0,012 7	0,030 6
	1,30	1,309 8	0,024 0	0,040 9
Mn	0,013 0	0,012 3	0,000 5	0,002 0
P	0,022	0,022 5	0,006 0	0,007 0
	0,090	0,089 2	0,009 0	0,010 6
Sb	0,23	0,236 6	0,014 6	0,018 1
As	0,130 0	0,137 3	0,011 0	0,015 5

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

9.4 Method D — Copper-aluminium alloys

Six laboratories co-operated in validating this method and obtained the results summarized in Table 28.

Table 28 — Method D — Statistical information

Element	Reference value %	Found %	Repeatability r	Reproducibility R
Sn	0,189	0,187 9	0,005 8	0,009 7
	0,199	0,200 3	0,011 2	0,016 9
	0,256	0,248 1	0,007 1	0,021 7
Pb	0,105	0,108 2	0,005 1	0,021 2
	0,149	0,153 0	0,007 7	0,013 4
	0,171	0,184 0	0,010 5	0,020 2
	0,229	0,230 2	0,011 6	0,012 7
Zn	0,314	0,327 6	0,012 1	0,027 9
	0,425	0,439 0	0,015 6	0,025 6
	0,501	0,527 3	0,023 6	0,038 1
	0,533	0,550 3	0,022 9	0,052 2
Fe	0,790	0,796 1	0,023 3	0,054 2
	0,806	0,813 2	0,017 3	0,061 6
	3,979	4,089 9	0,119 2	0,182 1
	6,085	6,074 6	0,098 6	0,338 0
Ni	0,819	0,824 1	0,017 5	0,041 1
	1,178	1,206 4	0,020 3	0,044 0
	3,865	3,864 9	0,083 1	0,202 1
	5,429	5,501 4	0,103 2	0,130 6
Mn	0,057	0,061 6	0,003 6	0,011 8
	1,84	1,864 9	0,019 2	0,093 1
Al	7,164	7,053 3	0,101 9	0,277 0
	10,956	10,946 4	0,147 2	0,199 2
	11,532	11,519 3	0,138 5	0,150 6
Cd	0,050 0	0,050 8	0,002 2	0,004 5
	0,069 5	0,070 2	0,002 8	0,005 8

NOTE 1 For Tin, it was decided to remove the precision data corresponding to a reference material labelled CA 35 (0,27 % content level), as it was assumed that this sample may be not enough homogeneous regarding to its Tin content.

NOTE 2 For Manganese, it was decided to remove the precision data corresponding to a reference material labelled CA 35 (1,56 % content level), as it was assumed that this sample may be not enough homogeneous regarding to its Manganese content.

NOTE 3 For Aluminium, it was decided to remove the precision data corresponding to a reference material labelled CA 20 (7,985 % content level), as it was assumed that this sample may be not enough homogeneous regarding to its Aluminium content.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

9.5 Method E — Copper-beryllium alloys

Five laboratories co-operated in validating this method and obtained the results summarized in Table 29.

Table 29 — Method E — Statistical information

Element	Reference value %	Found %	Repeatability r	Reproducibility R
Sn	0,022	0,021 5	0,001 7	0,003 1
	0,100	0,097 4	0,003 5	0,009 3
Pb	0,023 4	0,023 2	0,002 5	0,002 6
	0,053	0,053 8	0,002 5	0,003 2
Zn	0,056	0,055 4	0,003 9	≤ *r*
	0,070	0,068 8	0,004 2	0,011 7
Fe	0,072	0,070 0	0,002 6	0,005 9
	0,165	0,163 4	0,004 1	0,011 7
	0,203	0,207 7	0,008 8	0,017 9
Ni	0,038 3	0,037 9	0,002 2	0,004 0
	0,049	0,048 4	0,002 0	0,003 9
	0,203	0,204 7	0,004 5	0,013 9
Mn	0,007 7	0,008 6	0,000 3	0,000 5
	0,019	0,019 7	0,000 3	0,000 6
Al	0,027	0,029 7	0,005 4	*r*
	≤			
	0,044 0	0,043 4	0,005 8	≤ *r*
Be	0,096	0,092 8	0,004 2	0,005 4
	0,18	0,159 3	0,003 6	0,003 9
	1,58	1,559 3	0,029 2	0,061 8
Co	2,92	2,873 2	0,060 8	0,127 3
	0,246	0,241 3	0,006 8	0,012 8
	0,64	0,635 7	0,009 8	0,024 0
	0,99	0,962 8	0,028 2	0,041 1

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

9.6 Method F — Copper-nickel alloys

Seven laboratories co-operated in validating this method and obtained the results summarized in Table 30.

Table 30 — Method F — Statistical information

Element	Reference value %	Found %	Repeatability r	Reproducibility R
Pb	0,055 3	0,056 7	0,006 5	0,008 5
Zn	0,474 7	0,474 4	0,011 3	0,040 5
Fe	1,532	1,519 4	0,043 8	0,072 9
Ni	7,775	7,871 7	0,144 4	0,183 1
	30,200	29,881 3	0,639 9	0,680 7
Mn	0,880	0,882 8	0,028 8	0,085 2
	2,7	2,822 3	0,078 9	0,192 9

NOTE For Iron, it was decided to remove the precision data corresponding to a reference material labelled NK (2,20 % content level), as it was assumed that this sample may be not enough homogeneous regarding to its Iron content.

10 Test report

The test report shall contain the following information:

a) identification of the test sample;

b) reference to this European Standard (EN 15605);

c) method used;

d) results;

e) any unusual characteristics noted during the determination;

f) any operation not included in this European Standard or in the document to which reference is made or regarded as optional;

g) date of the test and/or date of preparation or signature of the test report;

h) signature of the responsible person.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

Annex A

(informative)

Optical emission spectrometer (OES) — Suggested performance criteria to be checked

A.1 Practical resolution of the sequential spectrometer

The resolution of a spectrometer can be defined as the wavelength difference, $\Delta\lambda$, between two lines which can still just be observed separately. In practice the parameter FWHM (Full Width at Half Maximum) is used as a resolution measure.

Ideally, the resolution should be of the same order as the physical line width in inductively coupled plasma optical emission spectrometer spectra, i.e. 2 pm to 5 pm (1 pm = 10^{-12} m). In practice, however, the observed width of the emission lines and, consequently, the resolution will often be determined by the bandwidth (r) of the spectrometer being used. As long as broadening resulting from aberrations can be neglected, this bandwidth is given by:

$$r = \text{FWHM} = (d\lambda/dx)\,(w_i + w_u)/2 \qquad \text{(A.1)}$$

where

w_i and w_u are the widths of the entrance slit and exit slit respectively;

$d\lambda/dx$ is the reciprocal linear dispersion which is given by:

$$d\lambda/dx = d(\cos\beta)/nL$$

where

L is the focal length of the spectrometer;

n is the order number;

d is the reciprocal of the groove density in the grating;

β is the diffraction angle.

Normally, commercial spectrometers present resolutions in the range of 4 pm to 30 pm. A good resolution is of great importance to cope with the frequent spectral interferences, which occur in inductively coupled plasma optical emission spectrometer. Since a line with a wavelength in the second order will have the same diffraction angle β as a line with a wavelength 2λ in the first order, a spectrometer should either have an order sorting possibility or an optical filter to avoid an order overlap.

A.2 Short and long term stability

The evaluation of the short-term stability consists on calculating the repeatability standard deviation of the inductively coupled plasma optical emission spectrometer.

A series of ten consecutive intensity measurements of the (high) multi-element calibration solution is carried out using the typical integration time for the system. The average I_{avrg} and standard deviation S_I of the ten measurements are calculated in addition to the relative standard deviation RSD_I, according to the following equation:

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

$$RSD_I = (S_I/I_{avrg}) \times 100\ (\%) \qquad (A.2)$$

In inductively coupled plasma optical emission spectrometer for solutions with concentrations of at least twice the background-equivalent concentration (BEC), RSD_I-values between 0,3 % and 1,0 % are generally accepted. Multi-element calibration solutions may be used for measurement at various analytical lines present in simultaneous optics.

Long term stability assessment is a measurement of the instrument drift. This is only required if the inductively coupled plasma optical emission spectrometer is set up to work for long intervals of time. It consists of carrying out the same short term stability tests at specific intervals of time, 15 min to 1 h, and plotting the deviation of the average found for every short term test against time. Deviations of more than 2 %/h should not be accepted. In case the instrument is not able to perform better, during analysis the control calibration solution should be measured more often and the mean results of the test sample solutions should be recalculated by interpolation between two consecutive control calibration solutions.

A.3 Evaluating the background equivalent concentration (BEC)

The BEC is used as a measure for instrument sensitivity. (Since the analyte signal has usually a relatively high background, its correction by the background intensity is recommended.). It is calculated using the following equation:

$$BEC = \frac{I_{BG}}{I_{net}} \times C_{Analyte} \qquad (A.3)$$

where

I_{BG} is the intensity of the background;

I_{net} is the intensity of the analyte (overall intensity minus intensity of the background);

$C_{Analyte}$ is the concentration of analyte that yields I_{net}.

The BEC values for the elements to be analysed can be found in wavelength tables (usually part of the instrument software). The BEC is the better the smaller its numerical value is.

A.4 Evaluating the limit of detection

To the blank test solution all the matrix determining components are added and respectively as much of the element concerned for solutions to be obtained with concentration levels of 0,5, 1,0, 1,5, 2,0, 3,0 and 5,0 times the estimated limit of detection.

All solutions are measured at least ten times (using the appropriate number of replicates).

The RSDs obtained are plotted against concentration and the graph obtained is used to read off the limit of detection.

This limit is the concentration at which the RSD is 33 %.

NOTE The limit of quantification is the concentration at which the RSD is 10 %.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

Annex B

(informative)

Inductively coupled plasma emission spectrometry method for the analysis of Copper-tin-lead alloys

B.1 Introduction

This informative annex specifies an inductively coupled plasma emission spectrometry method for the determination of alloying elements and impurities in Copper-tin-lead alloys in the form of unwrought, wrought and cast products.

This method is applicable to the elements listed in Table B.1 within the composition ranges shown:

Table B.1 – Copper-tin-lead alloys

Element	Mass fraction %	
	min.	max.
Sn	3,00	12,00
Pb	8,00	25,00
Zn	0,05	3,00
Fe	0,01	0,50
Ni	0,05	3,00
Mn	0,01	0,30
P	0,02	0,40
Al	0,01	0,40
Sb	0,02	0,80

NOTE 1 The ranges specified can be extended or adapted, for the determination of lower mass fractions.

NOTE 2 Other elements may be included. However such elements and their mass fractions should be carefully checked, taking into account interference, sensitivity, resolution and linearity criteria for each instrument and each wavelength.

B.2 Principle

Dissolution of a test portion with hydrochloric and nitric acids. After suitable dilution and addition of an internal reference element, nebulization of the solution into an inductively coupled plasma emission spectrometer and measurement of the intensity of the emitted light including that of the internal reference element.

B.3 Reagents

Refer to Clause 4 of this standard.

B.4 Apparatus

Refer to Clause 5 of this standard.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

B.5 Sampling

Refer to Clause 6 of this standard.

B.6 Procedure

B.6.1 Preparation of the test portion solution

B.6.1.1 Test portion

Weigh (0,500 ± 0,001) g of the sample.

B.6.1.2 Test portion solution 2,5 g/l

Transfer the test portion (7.7.1.1) into a 250 ml beaker.

Add 10 ml of hydrochloric acid (4.2) and 2,5 ml of nitric acid (4.3). Cover with a watch glass and dissolve the sample at room temperature. When the sample is completely dissolved add about 40 ml of water and heat to boiling. If a $PbCl_2$ precipitate is present, heat the solution to just below the boiling point and maintain this temperature as long as necessary to dissolve the precipitate. Allow to cool.

Rinse the cover and the walls of the beaker with water.

Transfer the dissolved test portion into a 200 ml one-mark volumetric flask containing 10 ml of hydrochloric acid (4.1).

Dilute to the mark with water and mix well.

B.6.1.3 Test portion solution 0,5 g/l

In order to obtain solutions with 0,5 g/l concentration, pipette exactly 20 ml of the test portion solution (B.6.1.2) into a 100 ml one-mark volumetric flask containing 5 ml of hydrochloric acid (4.1) and 5 ml of yttrium solution (4.34). Dilute to the mark with water and mix well.

B.6.2 Check test

Make a preliminary check of the apparatus by preparing a solution of a leaded tin bronze reference material or a synthetic sample containing known amounts of the elements listed in Table B.1 and carrying out the procedure specified in B.6.4.

B.6.3 Establishment of the calibration curves

B.6.3.1 Preparation of the calibration solutions

B.6.3.1.1 General

In all cases the acidity of the calibration solutions shall be similar to those of the test portion solutions.

B.6.3.1.2 Preparation of the 2,5 g/l calibration solutions, using mono-elemental solutions

Weigh the quantities of copper (4.7) shown in Table B.2 and introduce them into each of a series of 250 ml beakers.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

Add 10 ml of hydrochloric acid solution (4.2) and 2,5 ml of nitric acid (4.3) to each beaker. Cover with a watch glass and heat gently in order to dissolve the copper. Rinse the cover and the walls of the beaker with water and heat to boiling. Allow to cool and transfer each copper solution into a 200 ml one-mark volumetric flask containing 10 ml of hydrochloric acid (4.1).

Add about 40 ml of water and then transfer the volumes of the elemental solutions of Pb at first, Sn, Zn, Fe, Ni, Mn, P, Sb and Al, shown in Table B.2 to each volumetric flask. Dilute to the mark with water and mix well.

B.6.3.1.3 Preparation of the 0,5 g/l calibration solutions

Dilute accurately the 2,5 g/l calibration solutions (B.6.3.1.2) in order to obtain 0,5 g/l calibration solutions.

Pipette exactly 20 ml of the 2,5 g/l calibration solutions (B.6.3.1.2) into a 100 ml one-mark volumetric flask containing 5 ml of hydrochloric acid (4.1) and 5 ml of yttrium solution (4.34). Dilute to the mark with water and mix well.

B.6.3.2 Adjustment of the apparatus

Start the inductively coupled plasma optical emission spectrometer and let it run for at least half an hour before performing any measurements.

Adjust all the instrumental parameters, each gas flow rate (outer, intermediate or central), torch position, entrance slits, exit slits, photomultiplier tubes voltages (when appropriate), wavelengths of the analytical lines specified in Table B.3, pre-spraying time and integrating time, according to the manufacturer's instructions, while aspirating (for each element) the highest concentration calibration solutions.

Prepare the software for the measurement of the intensity of each analytical line and for the calculation of the corresponding mean value and relative standard deviation.

Each time the internal standard is used (Y line 371,03 nm) prepare the software to calculate the ratio between each analyte intensity and internal standard intensity.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

Table B.2 — Composition of the 2,5 g/l calibration solutions

Element	Label			Drift survey solution
	F9	F10	F11	(see B.6.3.3)
Cu (4.7)	378,4 mg 75,68 %	357,7 mg 71,54 %	359,45 mg 71,89 %	356,5 mg 71,30 %
Sn (4.30)	45,0 mg 9 ml 9,00 %	15,0 mg 3 ml 3,00 %	60,0 mg 12 ml 12,00 %	30,0 mg 6 ml 6,00 %
Pb (4.20)	70,0 mg 14 ml 14,00 %	125,0 mg 25 ml 25,00 %	40,0 mg 8 ml 8,00 %	100,0 mg 20 ml 20,00 %
Zn (4.33)	2,50 mg 2,5 ml 0,50 %	0,25 mg [a] 0,05 %	15,0 mg 15 ml 3,00 %	5,0 mg 5 ml 1,00 %
Fe (4.19)	0,25 mg [b] 0,05 %	0,05 mg [c] 0,01 %	2,5 mg 2,5 ml 0,50 %	1,0 mg 1 ml 0,20 %
Ni (4.27)	2,50 mg 2,5 ml 0,50 %	0,25 mg [d] 0,05 %	15,0 mg 15 ml 3,00 %	5,0 mg 5 ml 1,00 %
Mn (4.24)	0,25 mg [e] 0,05 %	1,5 mg [f] 0,30 %	0,05 mg [g] 0,01 %	0,50 mg [h] 0,10 %
P (4.28)	0,30 mg [i] 0,06 %	0,1 mg [j] 0,02 %	2,0 mg 2 ml 0,40 %	0,50 mg [k] 0,10 %
Sb (4.11)	0,4 mg [l] 0,08 %	0,1 mg [m] 0,02 %	4,0 mg 4 ml 0,80 %	1,0 mg 1 ml 0,20 %
Al (4.10)	0,4 mg [n] 0,08 %	0,05 mg [o] 0,01 %	2,0 mg 2 ml 0,40 %	0,50 mg [p] 0,10 %

[a] 2,5 ml of a 0,1 g/l zinc stock solution.
[b] 5 ml of a 0,05 g/l iron stock solution.
[c] 1 ml of a 0,05 g/l iron stock solution.
[d] 2,5 ml of a 0,1 g/l nickel stock solution.
[e] 2,5 ml of a 0,1 g/l manganese stock solution.
[f] 15 ml of a 0,1 g/l manganese stock solution.
[g] 5 ml of a 0,01 g/l manganese stock solution.
[h] 5 ml of a 0,1 g/l manganese stock solution.
[i] 3 ml of a 0,1 g/l phosphorus stock solution.
[j] 1 ml of a 0,1 g/l phosphorus stock solution.
[k] 5 ml of a 0,1 g/l phosphorus stock solution.
[l] 4 ml of a 0,1 g/l antimony stock solution.
[m] 1 ml of a 0,1 g/l antimony stock solution.
[n] 4 ml of a 0,1 g/l aluminium stock solution.
[o] 5 ml of a 0,01 g/l aluminium stock solution.
[p] 5 ml of a 0,1 g/l aluminium stock solution.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

Table B.3 — Wavelengths for determination in copper-tin-lead alloys

Element	Wavelength
	nm
Sn	189,90
Pb	220,30
Zn[a]	334,55
Fe	238,20
Ni	231,60
Mn	257,60
P	178,23
Al	308,20
Sb	206,80

[a] 213,80 nm wavelength may be used to determine zinc, provided that interference from copper has been investigated.

B.6.3.3 Spectrometric measurements of the calibration solutions

Carry out the spectrometric measurements of the 0,5 g/l solutions identified E9, E10, E11 (see Table B.2 and B.6.3.1.3). For phosphorus use the 2,5 g/l calibration solutions (B.6.3.1.2). A simultaneous spectrometer shall be available for measurements using yttrium as "internal standard" (ratio mode).

For phosphorus determination use "absolute intensity" taking into account that "Gaussian" measuring mode may also be recommended.

For each calibration solution (including the "drift survey" solution) at least three integrations are necessary in order to calculate the mean ratioed intensities (mean absolute intensity for phosphorus).

In order to control the drift of the spectrometer, analyse the "drift survey" solution (see Table B.2 and B.6.3.1.3) at least once for every five test portion solutions. Maximum drifts allowed are given in Table B.4.

Table B.4 — Drift survey for copper-tin-lead alloys

Element	Concentration range	Maximum drift
	%	%
all	0,1 to 0,5	0,02
	0,5 to 2,0	0,05
	2,0 to 10,0	0,1
	10,0 to 50,0	0,2

B.6.3.4 Calibration curves

Establish the calibration curves using measured ratioed intensities (absolute intensity for phosphorus) and corresponding analyte amounts.

Use appropriate spectrometer software for regression calculations and calculate the corresponding correlation coefficients: these coefficients should be, at least, 0,999.

B.6.4 Determination

B.6.4.1 General

The analyses shall be carried out independently, in duplicate.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

B.6.4.2 Spectrometric measurement

Carry out measurements on the test solution (B.6.1.3) (B.6.1.2 for phosphorus).

Determine the contents directly using the calibration curves (B.6.3.4).

B.7 Expression of results

The calibration curves are drawn from the measurements carried out either in the "ratio" or in "intensity" mode according to the concentrations of the various elements. On the calibration curves, read the contents, expressed as mass fraction in percent of the elements determined in the test sample.

B.8 Precision

Six laboratories co-operated in validating this method and obtained the results summarized in Table B.5.

Table B.5 — Statistical information

Element	Reference value %	Found %	Repeatability r	Reproducibility R
Sn	9,35	9,316 9	0,227 7	0,332 5
Pb	9,25	9,093 5	0,157 0	0,296 4
Zn	0,13	0,138 8	0,011 0	0,044 4
Ni	0,28	0,276 8	0,012 2	0,013 8
P	0,056	0,053 8	0,012 5	0,017 2
Sb	0,18	0,187 4	0,016 3	0,019 9

NOTE As stated in the Scope, the precision criteria concerning this method do not reach the suitable level, namely for zinc and for phosphorus.

B.9 Test report

Refer to Clause 10 of this standard.

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

Bibliography

[1] ISO 5725-1, *Accuracy (trueness and precision) of measurement methods and results — Part 1: General principles and definitions*

[2] ISO 5725-2, *Accuracy (trueness and precision) of measurement methods and results — Part 2: Basic method for the determination of repeatability and reproducibility of a standard measurement method*

[3] ISO 5725-3, *Accuracy (trueness and precision) of measurement methods and results — Part 3: Intermediate measures of the precision of a standard measurement method*

[4] V. Rigaux, M. Pelé, S. Ryser, *Application de la spectrométrie d'émission avec plasma à l'analyse des alliages cuivreux*; Analysis, 1989, v. 17, n° 6, pp. 297-307

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

This page deliberately left blank

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

This page deliberately left blank

Provided by IHS
No reproduction or networking permitted without license from IHS
Not for Resale

British Standards Institution (BSI)

BSI is the independent national body responsible for preparing British Standards and other standards-related publications, information and services.
It presents the UK view on standards in Europe and at the international level.

It is incorporated by Royal Charter.

Revisions

British Standards are updated by amendment or revision. Users of British Standards should make sure that they possess the latest amendments or editions.

It is the constant aim of BSI to improve the quality of our products and services. We would be grateful if anyone finding an inaccuracy or ambiguity while using this British Standard would inform the Secretary of the technical committee responsible, the identity of which can be found on the inside front cover.

Tel: +44 (0)20 8996 9001 Fax: +44 (0)20 8996 7001

BSI offers Members an individual updating service called PLUS which ensures
that subscribers automatically receive the latest editions of standards.

Tel: +44 (0)20 8996 7669 Fax: +44 (0)20 8996 7001
Email: plus@bsigroup.com

Buying standards

You may buy PDF and hard copy versions of standards directly using a credit card from the BSI Shop on the website www.bsigroup.com/shop.
In addition all orders for BSI, international and foreign standards publications can be addressed to BSI Customer Services.

Tel: +44 (0)20 8996 9001 Fax: +44 (0)20 8996 7001
Email: orders@bsigroup.com

In response to orders for international standards, it is BSI policy to supply the BSI implementation of those that have been published as British Standards, unless otherwise requested.

Information on standards

BSI provides a wide range of information on national, European
and international standards through its Knowledge Centre.
Tel: +44 (0)20 8996 7004 Fax: +44 (0)20 8996 7005
Email: knowledgecentre@bsigroup.com

Various BSI electronic information services are also available which
give details on all its products and services.
Tel: +44 (0)20 8996 7111 Fax: +44 (0)20 8996 7048
Email: info@bsigroup.com

BSI Subscribing Members are kept up to date with standards developments and receive substantial discounts on the purchase price of standards. For details of these and other benefits contact Membership Ad-
ministration.

Tel: +44 (0)20 8996 7002 Fax: +44 (0)20 8996 7001
Email: membership@bsigroup.com

Information regarding online access to British Standards via British Standards Online can be found at www.bsigroup.com/BSOL

Further information about BSI is available on the BSI website at www.bsigroup.com/standards

Copyright

Copyright subsists in all BSI publications. BSI also holds the copyright, in the UK, of the publications of the international standardization bodies. Ex-
cept as permitted under the Copyright, Designs and Patents Act 1988 no ex-
tract may be reproduced, stored in a retrieval system or transmitted in any form or by any means – electronic, photocopying, recording or otherwise – without prior written permission from BSI. This does not preclude the free use, in the course of implementing the standard of necessary details such as
symbols, and size, type or grade designations. If these details are to be used
for any other purpose than implementation then the prior written permission
of BSI must be obtained. Details and advice can be obtained from the Copy-
right & Licensing Manager.

Tel: +44 (0)20 8996 7070
Email: copyright@bsigroup.com

BSI Group Headquarters

389 Chiswick High Road London W4 4AL UK

Tel +44 (0)20 8996 9001
Fax +44 (0)20 8996 7001
www.bsigroup.com/standards

raising standards worldwide™

Provided by IHS
No reproduction or networking permitted without license from IHS

Not for Resale