

BS ISO 5348:2021



BSI Standards Publication

**Mechanical vibration and shock —
Mechanical mounting of accelerometers**

National foreword

This British Standard is the UK implementation of [ISO 5348:2021](#). It supersedes BS ISO 5348:1998, which is withdrawn.

The UK participation in its preparation was entrusted to Technical Committee GME/21/5, Vibration of machines, vehicles and structures.

A list of organizations represented on this committee can be obtained on request to its committee manager.

This publication does not purport to include all the necessary provisions of a contract. Users are responsible for its correct application.

© The British Standards Institution 2021
Published by BSI Standards Limited 2021

ISBN 978 0 539 04489 8

ICS 17.160

Compliance with a British Standard cannot confer immunity from legal obligations.

This British Standard was published under the authority of the Standards Policy and Strategy Committee on 28 February 2021.

Amendments/corrigenda issued since publication

Date	Text affected
------	---------------

INTERNATIONAL STANDARD

ISO
5348

Third edition
2021-01-29

Mechanical vibration and shock — Mechanical mounting of accelerometers

*Vibrations et chocs mécaniques — Fixation mécanique des
accéléromètres*



Reference number
ISO 5348:2021(E)

© ISO 2021



COPYRIGHT PROTECTED DOCUMENT

© ISO 2021, Published in Switzerland

All rights reserved. Unless otherwise specified, no part of this publication may be reproduced or utilized otherwise in any form or by any means, electronic or mechanical, including photocopying, or posting on the internet or an intranet, without prior written permission. Permission can be requested from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office
Ch. de Blandonnet 8 • CP 401
CH-1214 Vernier, Geneva, Switzerland
Tel. +41 22 749 01 11
Fax +41 22 749 09 47
copyright@iso.org
www.iso.org

Contents		Page
Foreword		iv
Introduction		v
1 Scope		1
2 Normative references		1
3 Terms and definitions		1
4 Basics		1
5 Characteristics to be specified by manufacturers of accelerometers		4
6 Considerations for selecting a mounting method		4
6.1 General considerations.....		4
6.1.1 Procedures.....		4
6.1.2 Conditions.....		4
6.2 Specific considerations.....		5
6.2.1 Frequency range of operation.....		5
6.2.2 Transducer cable.....		5
6.3 Determination of the mounted fundamental resonance frequency.....		6
6.3.1 General.....		6
6.3.2 Vibration excitation method.....		6
6.3.3 Shock excitation methods.....		7
6.4 Recommendations for particular types of mountings.....		8
6.4.1 General.....		8
6.4.2 Stud mounting.....		9
6.4.3 Adhesive mounting.....		10
6.4.4 Magnets.....		13
6.4.5 Quick mount.....		13
6.4.6 Probe.....		14
6.4.7 Conical bolting.....		14
6.4.8 Low-percussion mounting devices for recording human exposure to vibration.....		15
6.4.9 Mounting by three-point support and ground spikes.....		15
6.4.10 Wedge anchors.....		15
6.4.11 Mounting fixtures.....		15
7 Typical frequency response for various types of mounting		16
8 Further mounting aspects		19
8.1 Base strain sensitivity of an accelerometer.....		19
8.2 Thermal mounting effects.....		19
8.3 Electrical ground loops.....		20
Bibliography		21

Foreword

ISO (the International Organization for Standardization) is a worldwide federation of national standards bodies (ISO member bodies). The work of preparing International Standards is normally carried out through ISO technical committees. Each member body interested in a subject for which a technical committee has been established has the right to be represented on that committee. International organizations, governmental and non-governmental, in liaison with ISO, also take part in the work. ISO collaborates closely with the International Electrotechnical Commission (IEC) on all matters of electrotechnical standardization.

The procedures used to develop this document and those intended for its further maintenance are described in the ISO/IEC Directives, Part 1. In particular, the different approval criteria needed for the different types of ISO documents should be noted. This document was drafted in accordance with the editorial rules of the ISO/IEC Directives, Part 2 (see www.iso.org/directives).

Attention is drawn to the possibility that some of the elements of this document may be the subject of patent rights. ISO shall not be held responsible for identifying any or all such patent rights. Details of any patent rights identified during the development of the document will be in the Introduction and/or on the ISO list of patent declarations received (see www.iso.org/patents).

Any trade name used in this document is information given for the convenience of users and does not constitute an endorsement.

For an explanation of the voluntary nature of standards, the meaning of ISO specific terms and expressions related to conformity assessment, as well as information about ISO's adherence to the World Trade Organization (WTO) principles in the Technical Barriers to Trade (TBT), see www.iso.org/iso/foreword.html.

This document was prepared by Technical Committee ISO/TC 108, *Mechanical vibration, shock and condition monitoring*.

This third edition cancels and replaces the second edition ([ISO 5348:1998](http://www.iso.org/iso/5348:1998)), which has been technically revised.

The main changes compared to the previous edition are as follows:

- the theory of mass and stiffness influence on the frequency response obtained has been expanded;
- the frequency responses have been replaced by actual measurements and have been made more comparable;
- the influence of electrical loops has been added.

Any feedback or questions on this document should be directed to the user's national standards body. A complete listing of these bodies can be found at www.iso.org/members.html.

Introduction

The method most commonly used for determining the vibratory motion of a structure or body is the use of an electromechanical vibration transducer, also called a transducer or a vibration sensor. These vibration transducers can be divided into the two broad classes: non-contacting and contacting transducers.

Non-contacting transducers are relative measuring transducers recording a motion in relation to a fixed space coordinate system. Typical examples are eddy-current probes, optical sensors and laser vibrometers. These transducers have no direct mechanical contact with the structure and are therefore not dealt with in this document.

Contacting transducers are mounted onto the structure by mechanical coupling. This includes, for example, piezoelectric, capacitive and piezoresistive accelerometers as well as seismic velocity transducers. These absolute measuring transducers record the motion by seismic forces from the space coordinate system onto which they are mounted. If such a transducer is mounted onto a structure, the properties of the mounting can significantly influence the frequency response of the structure as well as the vibration transducer. Very large measurement deviations can occur in case of lack of care in the mounting property, particularly at high frequencies.

Under certain circumstances the mass, geometry and mounting stiffness of the transducer can directly influence the measured vibration amplitude of the structure. This effect occurs for example if the masses of the transducer and the structure are in the same order of magnitude.

This document is concerned with the contacting type of seismic accelerometers and seismic velocity transducers which are currently in wide use. The concern with using such transducers is that the mechanical coupling between the accelerometer and the test structure can significantly alter the response of the accelerometer, the structure or both. This document attempts to isolate parameters of concern in the selection of a method to mount the accelerometer onto the structure.

In a basic sense, many aspects of velocity transducer mounting are similar to those of accelerometers, but they are not identical. Please refer to [6.2.1](#).

This document does not cover geophones.

Mechanical vibration and shock — Mechanical mounting of accelerometers

1 Scope

This document specifies the important technical properties of the different methods for mounting vibration transducers and describes recommended practices. It also shows examples of how accelerometer mounting can influence frequency response and gives examples of how other influences can affect the fidelity of the representation of actual motion in the structure being observed.

This document applies to the contacting type of accelerometer which is currently in wide use. It is applicable to both uniaxial and multi-axial transducers. This document can also be applied to velocity transducers.

This document enables the user to estimate the limitations of a mounting and consequent potential measurement deviations.

Transducer mounting issues are not the only problem that can affect the validity of acceleration measurement. Other such problems include, amongst others: transverse movements, alignment of the transducer, base bending, cable movement, temperature changes, electric and magnetic fields, cable whip and mounting torque. Issues other than mounting and their possible effects are outside the scope of this document.

2 Normative references

The following documents are referred to in the text in such a way that some or all of their content constitutes requirements of this document. For dated references, only the edition cited applies. For undated references, the latest edition of the referenced document (including any amendments) applies.

[ISO 2041](#), *Mechanical vibration, shock and condition monitoring — Vocabulary*

[ISO 8042](#), *Shock and vibration measurements — Characteristics to be specified for seismic pick-ups*

3 Terms and definitions

For the purposes of this document, the terms and definitions given in [ISO 2041](#) apply.


ISO and IEC maintain terminological databases for use in standardization at the following addresses:

- ISO Online browsing platform: available at <https://www.iso.org/obp>
- IEC Electropedia: available at <http://www.electropedia.org/>

4 Basics

A vibration transducer is mounted on the surface of a structure in motion, as illustrated in the simplified diagram shown in [Figure 1](#). Under ideal conditions, the vibration transducer supplies an electric signal at its output which is proportional to the magnitude of the mechanical acceleration input vector, a_N . The vector a_N is normally directed to the transducer base and measures the projection of the structure vibration acceleration vector, a_S , in the direction of the transducer nominal sensitive vectorial axis, a_N (measurement direction).

The vibration in the direction of the acceleration vector, a_S , on the structure is transferred into the measurement direction of the transducer via the mechanical mounting fixture. Frequency-dependent



Key

- a_N accelerometer nominal axis perpendicular to its coupling mounting area (a^N_X, a^N_Y, a^N_Z)
- a_S structure vibration acceleration vector (a^S_X, a^S_Y, a^S_Z)
- a_T transducer vibration acceleration vector with largest sensitivity (a^T_X, a^T_Y, a^T_Z)
- φ angle between a_N and a_T
- α_1 angle between a_N and a_S
- α_2 angle between a_S and a_T
- 1 axis of minimum cross sensitivity
- 2 axis of maximum cross sensitivity
- 3 red dot, assigning minimal cross axis sensitivity axis
- 4 cross sensitivity vector

NOTE For exact measurement of the structure vibration, the vectors a_S and a_N are ideally identical in amount and direction; see [6.1.1](#).

Figure 2 — Acceleration vector considerations for mounting the accelerometer

5 Characteristics to be specified by manufacturers of accelerometers

The technical characteristics of vibration transducers shall be specified in accordance with [ISO 8042](#) in the data sheet or manual. From a multitude of information items, only a few are relevant for the mounting of transducers:

- a) frequency response under well-defined mounting conditions, range of operation and best possible mounting;
- b) mounting surface of the transducer: dimensions of the mounting surface, mounting options, thread dimensions, thread depths, sectional view of the mounting surface, material of the mounting surface, surface finish roughness, surface flatness, hole perpendicularity and tap class;
- c) applicable recommended mounting torque and, as an option, the maximum permitted mounting torque;
- d) geometric dimensions of the vibration transducer, including:
 - position of the centre of gravity of the vibration transducer as a whole,
 - position of the centre of gravity of the seismic mass of the vibration transducer;
- e) pertinent mechanical characteristics of the accelerometer, i.e.:
 - total mass of the vibration transducer,
 - material of the base,
 - maximal transverse sensitivity and frequency at which it was determined;
- f) first resonance frequency of the vibration transducer under mounting conditions;
- g) temperature limitations of the transducer and the fastening device.

6 Considerations for selecting a mounting method

6.1 General considerations

6.1.1 Procedures

An accelerometer achieves optimal performance only if the following general procedures are followed:

- a) The accelerometer shall perform as closely as possible the same motion as the structure at the accelerometer attachment.
- b) The motion of the structure is changed as little as possible by the addition of the accelerometer, for example, by mass loading and reinforcement in the mounting surface area.

6.1.2 Conditions

In order to achieve the aforementioned ideal conditions, it shall be ensured that:

- a) the accelerometer and its mounting are as rigid and firm as possible and the mounting surfaces are as clean and flat as possible;
- b) distortions due to natural vibrations of the mounting are only very small (e.g. symmetrical mountings shall be aimed at);
- c) the mass of the accelerometer and mounting are small in comparison with that of the dynamic mass of the structure (see [ISO 2954](#)).

6.2 Specific considerations

6.2.1 Frequency range of operation

The accelerometer shall be used well below its mounted fundamental resonance frequency to prevent amplitude distortions. In the case of undamped accelerometers (resonance magnification factor, Q , greater 30 dB) and mounting in accordance with manufacturer's recommendations, the following limit frequencies can be used for estimation of the amplitude deviations:

- the amplitude deviations of the transducer are mostly lower than 5 % for up to approximately 20 % of the resonance frequency of the transducer;
- the amplitude deviations are mostly lower than 10 % for up to approximately 30 % of the resonance frequency;
- the amplitude deviations are mostly lower than 3 dB for up to approximately 50 % of the resonance frequency.

NOTE 1 Special measurement methods exist, for example, in the rolling bearing condition monitoring that operates in the resonance range of the accelerometer.


NOTE 2 For single-shock measurements, deviations of a few percent can be expected if the mounted fundamental resonance frequency is ten times greater than the inverse of the pulse duration.

NOTE 3 Electrodynamic vibration velocity transducers are mostly used above their resonance frequency.

6.2.2 Transducer cable

Relative movement of the cable to the transducer can lead to incorrect measurement signals, in particular in the case of stiff cables. Careful clamping and laying of the cables is required to avoid this problem (see [Figure 3](#)).

Loose, moving cables can introduce triboelectric effects for piezoelectric type transducers with charge output or impose dynamic response on the transducer not consistent with the motion of the tested surface.



a) Accelerometer with axial connector

b) Accelerometer with radial connector

Key

- 1 cable entry — do not stress
- 2 vibrating surface
- 3 cable entry — do not stress
- 4 fix cable to the surface

Figure 3 — Accelerometer with axial and radial connectors

6.3 Determination of the mounted fundamental resonance frequency

6.3.1 General

It is very useful, although difficult at times in practice, to accurately determine the mounted fundamental resonance frequency of the accelerometer mounted on a structure. The resonance frequency in the nominal measuring direction can vary widely from that in the lateral direction (which is usually lower). For multi-axial accelerometers, the resonance frequencies of the axes can vary considerably.

The following methods can be of use in determining the approximate resonance frequency, thus ensuring that an adequate margin exists between the resonance frequency and test frequency.

6.3.2 Vibration excitation method

A suitable electrodynamic vibration exciter with reference transducer can be used to assess the influence of the quality of mounting surfaces and materials. For this purpose, the materials under test are mounted between the armature of the vibration exciter and the transducer and its output signal as a function of the vibration frequency is measured.

For the method of determining the fundamental (resonance) frequency, see [ISO 5347-22](#) and [ISO 16063-32](#).

6.3.3 Shock excitation methods

For the method of determining the mounted fundamental resonance frequency by shock excitation, see [ISO 16063-32](#). Beside [ISO 16063-32](#), the following measurement technologies are also in use: the pendulum impact test, the drop test, a simple hammer blow and breakage of a pencil lead.

In the first case, the accelerometer is attached to a counterweight suspended from a pendulum while a similarly suspended weight acts as a hammer providing the blow.


In the drop test, the accelerometer is mounted onto a hammer which is guided in its vertical fall onto a stationary anvil to provide the shock. The mounting of the accelerometer to the weight should be similar to the test body (actual structure under test) mounting. When it is impossible to represent the test body by the mass of the hammer or anvil in a realistic way, the weight should be made of the same material and of sufficient size to be a reasonable representation of the test body in terms of stiffness.

One hammer blow applied near the mounted accelerometer on the actual structure can provide the necessary information, if structural resonances in the test body can be disregarded.

The accelerometer output signal produced by the shock under suitable conditions has the resonance frequency superimposed (see [Figure 4](#)) in cases where the shock duration, t_s , is shorter than $5/f_{Res}$, where f_{Res} is the lowest mounted fundamental resonance frequency of the accelerometer.

Some experimentation is required with the energy of shock (i.e. the height from which the weight is released) and the stiffness of the impact surface (e.g. steel or lead lined) to obtain a suitable period of impact for displaying the resonance effects. The lowest resonance should be excited during the shock. The use of a suitable single-event recorder, for example, a storage oscilloscope, enables the frequency of the resonance ripple (i.e. of the oscillations) to be determined. These methods are particularly suited for high frequencies.

When repeated, consistently well-defined shocks can give additional information about the stability of the mounting.




Key

- X time
- Y acceleration
- 1 shock response with resonance ripple

Figure 4 — Accelerometer response to shock at shock duration $t_s < 5/f_{Res}$

A broadband shock response spectrum can be generated by breaking a pencil lead (preferably with a diameter of 0,5 mm and a hardness of 2H) in the direction of the sensitive axis of the accelerometer under test in the vicinity of the mounting area. For this purpose, a commercially available mechanical pencil is equipped with a plastic moulded part which specifies the breaking angle and prevents bouncing (see ASTM E976). Here the shock duration, t_S , is shorter than $1/f_{Res}$ and the accelerometer under test is excited in its lowest fundamental mounted resonance frequency^[16], as shown in [Figure 5](#).



key

- X time
- Y accelerometer output signal
- a input shock pulse (approx. dirac pulse)
- b typical impulse response of an accelerometer (resonance oscillation)

Figure 5 — Accelerometer response to shock (idealized illustration)

6.4 Recommendations for particular types of mountings

6.4.1 General

The mounting surface on the structure shall be carefully examined for smoothness and contamination and, if necessary, it shall be machined flat. The size of the contact area of magnets, adhesive mounting pads and other mounting parts should be at least as large as the mounting surface of the transducer. If possible, any lack of alignment between the sensitive axis of the accelerometer and the measurement direction shall be kept to a minimum; otherwise this can lead to deviations introduced by angular deviation and transverse sensitivity. These deviations can be particularly large if the transverse motion is much greater than the axial motion.

The higher the frequency to be measured, the higher the static mounting force and the stiffness of the mounting should be.

The masses of the transducer and fastening material and the resonant cable should be as low as possible in order to minimize the influence on the measurement object.

For vibration measurements on electrical machines, it can be necessary to mount the transducer in an isolated manner in order to prevent ground loops (see [8.3](#)).

The condition of the mounting surface and method of mounting should be stated in reports.

In order to meet the manufacturer's specification, the recommended mounting method for the transducer should be used.

[Table 1](#) provides an overview of criteria for the selection of mounting methods, based on best practices.

Table 1 — Criteria for the selection of mounting methods

Attachment fidelity	Resonance frequency	Static strength	Temperature resistance	Importance of surface preparation
<p style="text-align: center;">High</p> <p style="text-align: center;">↑</p> <p style="text-align: center;">Low</p>	Stud or screw	Stud or screw	Stud or screw	Stud or screw
	Cyanoacrylate or epoxy resin adhesive	Cyanoacrylate or epoxy resin adhesive	Magnet	Cyanoacrylate
	Sticky wax	Thin double-sided tape	Cyanoacrylate or epoxy resin adhesive	Magnet
	Thin double-sided tape	Magnet	Hand-held probe tip	Sticky wax
	Cyanoacrylate or epoxy resin adhesive with adhesive mounting pad	Sticky wax	Thin double-sided tape	Thin double-sided tape
	Thin double-sided tape with adhesive mounting pad	Hand-held probe tip	Sticky wax	Epoxy resin adhesive
	Magnet			Hand-held probe tip
	Hand-held probe tip			


6.4.2 Stud mounting

6.4.2.1 The surfaces shall be clean, flat and machined smooth to manufacturer's tolerances if so specified. The axes of the stud mounting holes shall be perpendicular to the mounting surfaces.

6.4.2.2 The manufacturer's recommended mounting torque shall be used to obtain a firm fastening without damaging the accelerometer.

6.4.2.3 A thin film of oil or grease between the surfaces helps to achieve good contact and thus maximum stiffness of the mounting (see [Figure 6](#)).

6.4.2.4 The stud shall not bottom in the mounting hole, as rigidity can be lost due to a small gap between the surfaces. It can also deform the transducer bottom and influence its properties, or even damage the transducer.




Key

- | | | | |
|---|---------------------------------------|---|--------------------------------------|
| 1 | transducer | 5 | mounting thread inside the structure |
| 2 | transducer base | 6 | mounting with oil film or grease |
| 3 | mounting stud | 7 | structure |
| 4 | mounting thread inside the transducer | | |

Figure 6 — Stud mounting

6.4.3 Adhesive mounting

This method (see [Figure 7](#)) can be used when no other fastening is possible, when the structure cannot be drilled, when electrical isolation of the accelerometer is necessary, or when the surface flatness is insufficient. If the transducer is to be kept free from adhesive or easily detachable, a disc-shaped adhesive mounting pad is glued to the structure. This pad is threaded on one side and plane on its other side.



a) Transducer directly glued

b) Transducer on mounting pad

key

- 1 transducer
- 2 transducer base
- 3 adhesive
- 4 structure
- 5 adhesive mounting pad, fixture

Figure 7 — Mounting by direct adhesive bonding or with an adhesive mounting pad

The surface shall be cleaned according to the adhesive manufacturer's recommendations. It is recommended to remove fat and oil from both mounting surfaces.

The bond shall be as thin as possible and shall just fill the gap between the transducer and the structure. The adhesive bonding process shall be carried out with corresponding contact pressure.

Hard adhesives such as two-component adhesives or hot-melt adhesives shall be used. Solvent-drying adhesives tend to remain soft internally, thus lowering the stiffness of the bond and consequently the resonance frequency.

Cyanoacrylate adhesives are only suitable for even and smooth surfaces. Epoxy resin-based adhesives with fillers can be used for uneven surfaces.

Thin double-sided tape is also suitable for fastening. Only film-based double-sided tapes with as low as possible thickness are recommended; thicknesses lower than 0,2 mm are customary. Foam-based tapes are generally unsuitable.

The ambient temperature during measurement is important for choosing suitable adhesives. Sticky wax should only be used at room temperature. The maximum application temperature of some cyanoacrylate adhesives is approximately 90 °C. Two-component adhesives or a different mounting option shall be used for higher temperatures. The ambient temperature during measurement is important for choosing suitable adhesives.

A bond should always exhibit a stiffness that is as high as possible. If the chemical properties and characteristics of the adhesive are known, the stiffness of the bond can be assessed as follows.

The mounted fundamental resonance frequency, f_c , can be estimated using [Formula \(1\)](#):

$$f_c = \frac{1}{2\pi} \sqrt{\frac{|K_c|}{m}} \quad (1)$$

where

K_c is the complex compressional stiffness of the bond;

m is the total mass, consisting of the mass of the transducer and any mounting adapters.

The complex compressional stiffness, K_c , of the bond can be estimated using [Formulae \(2\)](#) and [\(3\)](#):

$$K_c = E(1+j\eta)A/d \quad (2)$$

$$|K_c| = \frac{\sqrt{1+\eta^2} \cdot E \cdot A}{d}$$

$$|K_c| \approx \frac{E \cdot A}{d} \text{ for } \eta \ll 1 \quad (3)$$

where

E is the elastic (Young's) modulus of the adhesive;

η is the loss factor of the adhesive;

A is the surface of the bond;

d is the thickness of the bond.

j is the imaginary unit [$\sqrt{-1}$]

The transverse resonance frequency of the bond can be estimated using [Formula \(4\)](#):

$$f_s = \frac{1}{2\pi} \sqrt{\frac{|K_s|}{m}} \quad (4)$$

where

K_s is the complex shear stiffness of the bond.

The shear stiffness can be estimated by using [Formulae \(5\)](#) and [\(6\)](#):

$$K_s = G(1+j\beta)A/d \quad (5)$$

$$|K_s| = \frac{\sqrt{1+\beta^2} \cdot G \cdot A}{d}$$

$$|K_s| \approx \frac{G \cdot A}{d} \text{ for } \beta \ll 1 \quad (6)$$

where

G is the shear modulus of the adhesive;

β is the shear loss factor.

In order to increase the usable frequency range of the mounted accelerometer, the adhesive should generally be lightly damped (i.e. η or β less than 0,01) and hard (i.e. high E and G values) and the bond should be thin.

In order to remove the adhesive from the transducer, it is recommended to dissolve the bond with a suitable solvent and to separate the transducer carefully under the impact of shear forces from the

bonding area. Adhesive residues remaining on the transducer may only be removed with solvents and under no circumstances with hard mechanical tools in order not to damage the mounting surface.

6.4.4 Magnets

Magnets are well suited for mounting of accelerometers during temporary measurements. Magnets with high clamping force, preferably made of rare-earth materials, should be used. The mounting surface shall be as smooth as possible to ensure direct contact over the widest area of the magnet. Both mounting surfaces should be in touch without any material in between. Care should be taken to ensure that the interface is such that rocking is prevented. Where isolation between the transducer and the unit under test is required, an isolation adapter between transducer and magnet is recommended. The prerequisite of the mounting with a magnet is a ferromagnetic structure. Alternatively, a ferromagnetic steel disc which is at least the size of the magnet can be glued onto the structure.

The quality of the surfaces of the structure and the quality of the magnet influence the frequency response of the transfer. A thin oil film can improve the motion transfer. Special magnets are provided for measurements on curved surfaces (see [Figure 8](#)).

The common magnetic materials often only allow for measurements up to approximately 80 °C, but magnets for higher temperatures are also available.

There is a risk when attaching the transducer to the magnet and when attaching the transducer and magnet combination to the structure that high damaging shock loads can occur. The shock load can be reduced by carefully sliding or rolling the magnet onto the transducer and structure.




Figure 8 — Mounting by a magnet

6.4.5 Quick mount

Quick mounts allow accelerometers to be fastened by easily manageable twist and lock or click and lock systems. Due to the various modes of action, this document does not explain quick mounts in detail. Resonance frequency and amplitude limits should be determined experimentally or taken from the manufacturer's manual, for example.


6.4.6 Probe

For vibration measurements on structures which do not permit the fastening of an accelerometer, probes are used which are screwed into the transducer base and pressed down by hand; see [Figure 9 a\)](#).

Alternatively, a better solution is shown in [Figure 9 b\)](#). The probe has a rounded tip which fits snugly into the counterbore that has been machined into the structure. The usable frequency range mostly extends up to a few hundred Hertz only. The measurement result is subject to strong subjective influences, in particular due to variations of measurement direction and contact pressure. Therefore, hand-held accelerometers should be used after careful evaluation of their suitability for the intended measurement or test.



a) Probe with tip



b) Probe with round tip in conical counterbore

Figure 9 — Hand-held probes

6.4.7 Conical bolting

Conical bolting represents a special design of screw fastening (see [Figure 10](#)). A 90° cone which ends in a threaded bolt is screwed into a respective mounting hole with 90° chamfer in the structure. The cone and threaded bolt can be firmly attached to the transducer base or designed as a mounting pad.

Transducers mounted with conical bolting can measure up to 10 kHz, but this needs to be verified in each case.

Conical bolting requires a high degree of concentricity for both faces fitting together.




Figure 10 — Mounting by conical bolting

6.4.8 Low-percussion mounting devices for recording human exposure to vibration

Specially shaped adapters for measurement of vibration in the palm are given, for example, in [ISO 10819](#). Hand-held and strap mounted adapters are shown in [ISO 5349-2](#). An adapter shaped as a mounting disc for measurement of vibration on the seat pan or backrest of occupied seats is specified, for example, in [ISO 10326-1](#).

6.4.9 Mounting by three-point support and ground spikes

For a three-point support, the vibration transducer is placed without particular measurements directly or with an adapter on a measurement object. This type of mounting is applied, for example, during measurement of human exposure to vibrations in buildings. Ground spikes are used for measurement of ground-borne vibration. These and comparable types of mounting are only used at low frequencies and low amplitudes (see [ISO/TS 14837-31](#)).

6.4.10 Wedge anchors

For mounting of accelerometers onto concrete and masonry, expansion anchors can be used which are fixed in a borehole with a screw, the head of which has a mounting hole. Threaded bolts placed by a powder-actuated tool can also be used. The thread is used for fastening the transducer. This type of mounting is used, for example, for measurement of vibration emissions in buildings and other building structures. It is only suitable for low frequencies (see [ISO/TS 14837-31](#)).


6.4.11 Mounting fixtures

Mounting fixtures, including electrical isolating studs, should be designed and manufactured of a suitable material, rigid, of minimum mass, with low moment of inertia and preferably have a symmetrical structure to the measurement direction. Brackets should be avoided if possible. When necessary, it is recommended that a small stiff metal cube be used, rigidly mounted to the structure, with machined surfaces drilled and tapped to accept stud mounting.

If the use of a complicated bracket is unavoidable, a test of its vibration modes and natural frequencies with the accelerometer mounted to it is desirable.

7 Typical frequency response for various types of mounting


Figures 11 and 12 show the frequency responses of accelerometers having a mass of 11 g and 27 g, respectively, for various types of mounting. In both cases, the bolted connection is the mounting with the highest mounted fundamental resonance frequency. All other mounting methods decrease the mounted fundamental resonance frequency and can prejudice the measurement. The resonance frequency shifts partly cause large changes of the frequency response in the working range of the transducer. The frequency response of the transducer in the working range is therefore dependent on the stiffness of the mounting. Normally, a decrease in stiffness of the mounting causes a frequency-dependent increase in the sensitivity coefficient in the upper working frequency range.



Key

- 1 stud mounted
- 2 cyanoacrylate glue
- 3 beeswax
- 4 thin double-sided adhesive tape
- 5 cyanoacrylate glue with mounting pad
- 6 beeswax with mounting pad
- 7 double-sided adhesive tape with mounting pad
- 8 magnetic mounting
- Y logarithmic accelerometer output in dB
- X frequency in Hz

Figure 11 — Measured frequency responses of an accelerometer having a transducer mass of 11 g for various types of mounting



Key

- 1 stud mounted
- 2 cyanoacrylate glue
- 3 beeswax
- 4 thin double-sided adhesive tape
- 5 cyanoacrylate glue with mounting pad
- 6 beeswax with mounting pad
- 7 double-sided adhesive tape with mounting pad

Y logarithmic accelerometer output in dB

X frequency in Hz

Figure 12 — Measured frequency responses of an accelerometer having a transducer mass of 27 g for various types of mounting

The following lists contain important mounting aspects which can have a positive impact on the quality of the respective mounting (stiffness).

Bolted connection:

- Perpendicularity between mounting point and transducer;
- Low roughness and high flatness of the mounting point and the mounting surface of the transducer;
- Use of the recommended or specified mounting torque of the transducer (according to data sheet);
- Use of a contact lubricant or assembly oil at the thread and contact point.

Adhesive fastening with cyanoacrylate, epoxy resin, cement adhesive:

- Low roughness and high flatness of the mounting point and the mounting surface of the transducer;
- High cleanliness of the surface, free of grease and particles;
- Low thickness of the bond;

- High contact pressure during adhesive bonding;
- Maximum application temperature of the adhesives shall be observed.

Adhesive fastening with double-sided tape:

- Low thickness of the tape and high elastic stiffness property of the tape;
- High cleanliness of the surface, free of grease and particles;
- Low roughness and high flatness of the mounting point and the mounting surface of the transducer;
- High contact pressure during adhesive bonding;
- Observe maximum application temperature.

Adhesive fastening with sticky wax (mounting wax for the transducer):

- Low thickness of sticky wax layer;
- High cleanliness and freedom from oil on the surface and mounting surface of the transducer;
- Observe restricted temperature range.

Fastening with magnet:

- As high as possible magnetic clamping force;
- Low roughness of the mounting surfaces;
- Large mounting surface of the magnet;
- For flat contact surfaces, apply a thin layer of oil or grease, consistent with the temperature range.


The exemplary frequency responses illustrated in [Figures 11](#) and [12](#) are based on the condition that the mass of the accelerometer is small in terms of the mass of the structure or, for large inhomogeneous structures, in terms of the partial mass in the vicinity of the transducer fastening. For cases other than this normal case, [Figure 13](#) indicates a qualitative trend for frequency responses.

For the mounted fundamental resonance frequency of an accelerometer, two extreme cases are distinguished which also correspond to various vibration modes of the spring-mass system in the transducer.

Case 1: The transducer is mounted on a heavy structure compared to the transducer mass. This case is based on the accelerometer data sheet providing a mounted resonance frequency and thus a resonance frequency which is much lower than that shown in case 2.

Case 2: The transducer is not mounted and is freely suspended. This results in a very high resonance frequency.

Between extreme cases 1 and 2, there are case 3, with non-rigid mounting, and case 4 with mounting onto a flexible lightweight structure. In case 3, a pre-resonance of mounting occurs which limits the usable frequency range. In case 4, the dynamic behaviour of the structure to be measured can fundamentally change by attaching the transducer.



Key

- 1 Case 1: Ideal mounting conditions mass of transducer \ll mass of structure.
- 2 Case 2: Not mounted to any structure.
- 3 Case 3: Loosely mounted to structure.
- 4 Case 4: Mounted onto a thin plate (case 3), mass of transducer \approx partial mass of structure.

NOTE See References [15] and [16].

Figure 13 — Influence of the mounting conditions on the frequency response

8 Further mounting aspects

8.1 Base strain sensitivity of an accelerometer

The accelerometer manufacturer should provide a value for base strain sensitivity according to [ISO 5347-13](#). Consideration should be given when mounting the accelerometer to ensure that the structure can exert an accelerometer base strain of sufficient magnitude to be a significant contribution of the measured output of the transducer, e.g. if the accelerometer is attached to a vibration node to the structure and a high contribution to the measurement signal is generated via the strain rate sensitivity of the base. In extreme cases, this can even lead to cancellation between the vibration signal and base strain signal. Such effects shall be taken into account during the mounting of the transducer.

8.2 Thermal mounting effects

If accelerometers are subjected to abrupt or quick temperature cycles, transient loads inducing low-frequency interferences occur due to the pyroelectric effect, in particular in piezoelectric type transducers with ferroelectric properties. With very sensitive accelerometers, even an air draft can cause considerable interference. In such cases, thermal isolation, for example, a cover of foam material, can help.

This parameter is defined as the transient temperature sensitivity in accordance with [ISO 5347-18](#).

If cooling or heating systems are present in the clamping area or surrounding area of the transducer, this should be taken into account.

8.3 Electrical ground loops

If the transducers, power supply and measuring instruments are grounded on different points, it is possible for electric currents to be induced due to the different potential of the individual grounding points. Compensating currents can then flow through the earthing cables or shields which influence or distort the measurement signal; see [Figure 14](#). This usually emerges from the fact that a mains-frequency dependent interference signal is superimposed on the measurement signal. Earth looping problems can often be caused by large electromagnetic fields, like in the environment of frequency inverters^[17].




Figure 14 — Earth loop: transducer and measuring amplifier with different earthing potentials

In order to avoid these disturbing effects, earth loops shall be disrupted. This can be achieved in different ways, for example, by isolated mounting of a transducer (see [Figures 15](#) and [16](#)).




Figure 15 — Ground isolation of the transducer by isolated mounting




Figure 16 — Transducer with ground-isolated housing

If isolated mounting is not possible, electrically isolated signal conditioners with floating inputs can be used.

In the case of transducers affected by surrounding alternating magnetic fields, a validation of signal quality to be independent from those influences can be necessary.

Bibliography

- [1] [ISO 2954](#), *Mechanical vibration of rotating and reciprocating machinery — Requirements for instruments for measuring vibration severity*
- [2] [ISO 5347-13](#), *Methods for the calibration of vibration and shock pick-ups — Part 13: Testing of base strain sensitivity*
- [3] [ISO 5347-18](#), *Methods for the calibration of vibration and shock pick-ups — Part 18: Testing of transient temperature sensitivity*
- [4] [ISO 5347-22](#), *Methods for the calibration of vibration and shock pick-ups — Part 22: Accelerometer resonance testing — General methods*
- [5] [ISO 5349-2](#), *Mechanical vibration — Measurement and evaluation of human exposure to hand-transmitted vibration — Part 2: Practical guidance for measurement at the workplace*
- [6] [ISO 7626-1](#), *Mechanical vibration and shock — Experimental determination of mechanical mobility — Part 1: Basic terms and definitions, and transducer specifications*
- [7] [ISO 10326-1](#), *Mechanical vibration — Laboratory method for evaluating vehicle seat vibration — Part 1: Basic requirements*
- [8] [ISO 10817-1](#), *Rotating shaft vibration measuring systems — Part 1: Relative and absolute sensing of radial vibration*
- [9] [ISO 10819](#), *Mechanical vibration and shock — Hand-arm vibration — Measurement and evaluation of the vibration transmissibility of gloves at the palm of the hand*
- [10] [ISO/TS 14837-31](#), *Mechanical vibration — Ground-borne noise and vibration arising from rail systems — Part 31: Guideline on field measurements for the evaluation of human exposure in buildings*
- [11] [ISO 16063-31](#), *Methods for the calibration of vibration and shock transducers — Part 31: Testing of transverse vibration sensitivity*
- [12] [ISO 16063-32](#), *Methods for the calibration of vibration and shock transducers — Part 32: Resonance testing — Testing the frequency and the phase response of accelerometers by means of shock excitation*
- [13] ASTM E976, *Standard guide for determining the reproducibility of acoustic emission sensor response*
- [14] VDI 3839Part 1, *Instructions on measuring and interpreting the vibrations of machines — General principles*
- [15] DUMONT M., COOK A., KINSLEY N. *Acceleration measurement optimization: Mounting considerations and sensor mass effect* in M. Mains (ed.), *Topics in Modal Analysis & Testing*, Volume 10, Conference Proceedings of the Society for Experimental Mechanics Series, p. 61, Springer 2016
- [16] DUMONT M., & KUNTZ D. PETZSCHE TH. *Testing methods for verification of a mounted accelerometer frequency response* in N. Dervilis (ed.), *Special Topics in Structural Dynamics*, Volume 6, Conference Proceedings of the Society for Experimental Mechanics Series, p. 53, Springer 2017
- [17] INSTRUCTION MANUAL K-SHEAR Accelerometers; Document No. 002-089e-07-06.pdf¹⁾

1) www.kistler.com

British Standards Institution (BSI)

BSI is the national body responsible for preparing British Standards and other standards-related publications, information and services.

BSI is incorporated by Royal Charter. British Standards and other standardization products are published by BSI Standards Limited.

About us

We bring together business, industry, government, consumers, innovators and others to shape their combined experience and expertise into standards-based solutions.

The knowledge embodied in our standards has been carefully assembled in a dependable format and refined through our open consultation process. Organizations of all sizes and across all sectors choose standards to help them achieve their goals.

Information on standards

We can provide you with the knowledge that your organization needs to succeed. Find out more about British Standards by visiting our website at bsigroup.com/standards or contacting our Customer Services team or Knowledge Centre.

Buying standards

You can buy and download PDF versions of BSI publications, including British and adopted European and international standards, through our website at bsigroup.com/shop, where hard copies can also be purchased.

If you need international and foreign standards from other Standards Development Organizations, hard copies can be ordered from our Customer Services team.

Copyright in BSI publications

All the content in BSI publications, including British Standards, is the property of and copyrighted by BSI or some person or entity that owns copyright in the information used (such as the international standardization bodies) and has formally licensed such information to BSI for commercial publication and use.

Save for the provisions below, you may not transfer, share or disseminate any portion of the standard to any other person. You may not adapt, distribute, commercially exploit or publicly display the standard or any portion thereof in any manner whatsoever without BSI's prior written consent.

Storing and using standards

Standards purchased in soft copy format:

- A British Standard purchased in soft copy format is licensed to a sole named user for personal or internal company use only.
- The standard may be stored on more than one device provided that it is accessible by the sole named user only and that only one copy is accessed at any one time.
- A single paper copy may be printed for personal or internal company use only.

Standards purchased in hard copy format:

- A British Standard purchased in hard copy format is for personal or internal company use only.
- It may not be further reproduced – in any format – to create an additional copy. This includes scanning of the document.

If you need more than one copy of the document, or if you wish to share the document on an internal network, you can save money by choosing a subscription product (see 'Subscriptions').

Reproducing extracts

For permission to reproduce content from BSI publications contact the BSI Copyright and Licensing team.

Subscriptions

Our range of subscription services are designed to make using standards easier for you. For further information on our subscription products go to bsigroup.com/subscriptions.

With **British Standards Online (BSOL)** you'll have instant access to over 55,000 British and adopted European and international standards from your desktop. It's available 24/7 and is refreshed daily so you'll always be up to date.

You can keep in touch with standards developments and receive substantial discounts on the purchase price of standards, both in single copy and subscription format, by becoming a **BSI Subscribing Member**.

PLUS is an updating service exclusive to BSI Subscribing Members. You will automatically receive the latest hard copy of your standards when they're revised or replaced.

To find out more about becoming a BSI Subscribing Member and the benefits of membership, please visit bsigroup.com/shop.

With a **Multi-User Network Licence (MUNL)** you are able to host standards publications on your intranet. Licences can cover as few or as many users as you wish. With updates supplied as soon as they're available, you can be sure your documentation is current. For further information, email cservices@bsigroup.com.

Revisions

Our British Standards and other publications are updated by amendment or revision.

We continually improve the quality of our products and services to benefit your business. If you find an inaccuracy or ambiguity within a British Standard or other BSI publication please inform the Knowledge Centre.

Useful Contacts

Customer Services

Tel: +44 345 086 9001

Email: cservices@bsigroup.com

Subscriptions

Tel: +44 345 086 9001

Email: subscriptions@bsigroup.com

Knowledge Centre

Tel: +44 20 8996 7004

Email: knowledgecentre@bsigroup.com

Copyright & Licensing

Tel: +44 20 8996 7070

Email: copyright@bsigroup.com

BSI Group Headquarters

389 Chiswick High Road London W4 4AL UK